

CENTRAL MAPPING AUTHORITY

GEODETIC SURVEY OF N.S.W.

GEODETIC STATION RECONNAISSANCE and MAINTENANCE REPORT

STATION: **DITTON** No.: **1836**

MAP SHEET SCALE 1:250 000 **WOLLONGONG**

INSPECTED BY: **G. KEEP** DATE: **21/7/81**

AUTHORITY: **C.M.A.** FIELD BOOK:

Description:
 1. Cleared by lanes bearing.....
 Note: Cross out word or words which do not apply

2. Mast & Vanes have been painted white & black respectively.
 from Trig. Mast

3. The station/pillar was unpiled/not unpiled/constructed on.....
 19..... dimensions now being:

Description of mark..... should be explicit, e.g., S/Steel Pillar Plate, Steel plug, Brass plug, Bolt, G.I. Pipe

Height of mark..... m. above rock/concrete; Mark is..... m. above G.L.

Height of Top Vanes to Top Mark/Pillar plate..... m. Diameter of Vanes (vertical)..... m.

Height of Cairn..... m. Diameter of Cairn..... m. Name Plate found/not found/placed.

Length of Mast..... m. (approximate if not unpiled)

4. A..... set in conc/rock has been placed/found, bearing..... ° M from Mast/Plug/Pillar

5. A..... set in conc/rock has been placed/found, bearing..... ° M from Mast/Plug/Pillar

6. A..... set in conc/rock has been placed/found, bearing..... ° M from Mast/Plug/Pillar

7. A..... set in conc/rock has been placed/found, bearing..... ° M from Mast/Plug/Pillar

8. Action required:..... New mast & vanes required, 360° clearing necessary, can't be rebuilt.

STANDPOINT:


Mark	Direction	Horiz. Distance	Height Difference	Mark	Direction	Horiz. Distance	Height Difference
			above standpt.				above standpt.
			below				below
			above standpt.				above standpt.
			below				below
			above standpt.				above standpt.
			below				below
			above standpt.				above standpt.
			below				below
			above standpt.				above standpt.
			below				below
			above standpt.				above standpt.
			below				below

Prepared by: *Geoffrey King 18/5/81* Checked:


Noted on U.T.M. Card

J. King 15.7.85 Checked

SR 2738-1



GS 24

STATION DITTON D 1836	<p>Owner's Name: Address: Phone:</p> <p>Current Occupant: Address: Phone:</p> <p style="text-align: center;">ACCESS</p> <p>Access Report of 21/7/1981 was found suitable/unsuitable. Cairn only found. Mast and vanes destroyed. No marks found. Cairn in poor condition and needs rebuilding. 360° clearing necessary</p> <p style="text-align: center;">Reference Map - Burratorang 1:25 000</p>
Beacon Diagram 	<p>This section to be completed by officer constructing pillar.</p> <p>Original station mark found/not found. Description of mark:</p> <p>Original beacon found/not found. Description of beacon:</p> <p>Height Top of Vanes to Top Markm. Height of markm. above G.L. below rock/conem. below</p> <p>Diameter of Vanesm. Height of Cairnm. Original Beacon has/has not been destroyed by me.</p>
	<p>Date</p> <p style="text-align: right;">Record of Station</p>