						_
GEODETIC STATION RECONNAISSANCE and MAINTENANCE REPORT	CE and MAINTENANCE REPORT		STATION: B	Bibbam	No.: 909	
Description:	Note: Cross out word or words which do not apply		MAP SHEET SCALE 1:250 000	BEGA		.
Cleared by lanes bearingfrom Trig. Mast	from Trig. Mast		INSPECTED BY:	G. KEEP	DATE: 16 /4 80	
Mast & Vanes have been painted white & black respectively.			AUTHORITY:		FIELD BOOK:	
The station/pillar was unpiled/not unpiled/constructed on	9, dimensions now being:	<u>r</u>	330 340	350 360	10 / 20 / 30	
Description of markshould be explicit, e.g., S/Steel Pillar Plate, Steel plug, Brass plug, Bolt, G.I. Pipe	e, Steel plug, Brass plug, Bolt, G.I. Pi		Station Diagram	North	Not to Scale	`4
Height of markm. below rock/concrete; Mark ism. below G.L.	m. above G.L.	; <u>/</u>				Q
Height of Top Vanes to Top Mark/Pillar plateກ.	Diameter of Vanes (vertical)m.	/ U/				, ;
Height of Cairn	Name Piate found/not found/placed.	β β				šò,
Length of Mastm. (approximate if not unpiled)		<u>, ουε</u>	/!			/ 60
4. Aset in conc/rock has been placed/found, bearing"M from Mast/Plug/Pillar	"" M from Mast/Plug/Pillar	/ 04	7-			$\overline{\lambda}$
Aset in conc/rock has been placed/found, bearing	"M from Mast/Plug/Pillar	<u>}c / </u>				/ of
Aset in conc/rock has been placed/found, bearing"M	"" M from Mast/Plug/Pillar	OBZ				80
Aset in conc/rock has been placed/found, bearing"M	""M from Mast/Plug/Pillar	0/2		+		80
8. Action required:	***************************************	seo	1			100
STANDPOINT:		\0;				\int
Mark Direction Horiz. Height Difference Mark	Direction Horiz. Height	Height Differance				10/
above standpt.		above standpt.				720
above standpt.		above below standpt.	\			Ζ
above standpr.		above standpt.				130
abowe standpt.		above standpt.				/
above standpt.						
above standpt.		above standpt.				46
above standpt.		above standpt,	2,10 / 200	190 180	170 160 150	7
Prenared by & Ko. m 24/7/00 Charled	Notation II T. M. Card . L. Leel Cl.	. b. delle		Still Charles		

Beacon Diagram		
	Not to Scale	Owner's Name:
		Address:
		Phone:
		Access Report of 1/2, 1/19 RAwas found suitable/unsuitable.
		This station not found. A search was made
		in a patch of dense limber where two locals
		had indicated.
		Information from locals indicates station is
		in run down condition and alot of clearing would
		be needed to use this station.
		For access, follow Electricity Commission track along
		132 kV/33 kV power lines from Evenmbene Dam road
This section to be completed by officer construction pillar,		from Jindabyne. Follow track to top af ridge and turn right,
Original station mark found/not found.		make own way to try site.
Description of mark:		
Original beacon found/not found.		
Description of beacon:	-	Date Record of Station
Height Top of Vanes to Top Markm	3_	
Height of markm. below rock/concm. below G.L.	_!	
Diameter of Vanes		
Original Beacon has/has not been destroyed by me.	<u> </u>	