

Batch 1631

LAND INFORMATION CENTRE

GEODETTIC SURVEY OF A.S.M.

GEODETTIC STATION: RECONNAISSANCE and MAINTENANCE REPORT

BUG - 1215

STATION: BUDGERY	No.: 1215
MAP SHEET SCALE 1:250 000	COBAR
INSPECTED BY: A. Sivertsen	DATE: 22.7.94
AUTHORITY: LIC	FIELD BOOK:

Description:

1. Cleared by lanes bearing lightly timbered 360° from Trig. Mast

2. Mast & Vanes have been painted white & black respectively. **NO BEACON**

3. The station/pillar was unpiled/~~not unpiled~~ constructed on 22.7.94 19....., dimensions now being:

Description of mark Trig Plug..... should be explicit, e.g., S/Steel Pillar Plate, Steel plug, Brass plug, Bolt, G.I. Pipe

Height of mark.....m. above rock/concrete; Mark is.....m. above G.L.

Height of Top Vanes to Top Mark/Pillar plate.....m. Diameter of Vanes (vertical).....m.

Height of Cairn.....m. Diameter of Cairn.....m. Name Plate found/not found/placed.

Length of Mast.....m. (approximate if not unpiled)

4. A. SSM..... set in conc/rock has been placed/found; bearing.....°M from Mast/Plug/Pillar

5. A. D. HOLE..... set in ~~conc~~/rock has been placed/found; bearing 295°M from Mast/Plug/Pillar

6. A..... set in conc/rock has been placed/found; bearing.....°M from Mast/Plug/Pillar

7. A..... set in conc/rock has been placed/found; bearing.....°M from Mast/Plug/Pillar

8. Action required:.....

STANDPOINT: <u>DRILL HOLE</u>			STANDPOINT: <u>TRIG PLUG</u>				
Mark	Direction	Horiz. Distance	Height Difference	Mark	Direction	Horiz. Distance	Height Difference
<u>Azimuth by SUN OBS to RO</u>	<u>0 00 00</u>	<u>105° 20'</u>	<u>10"</u> above standpt.	<u>RO</u>	<u>0 00 00</u>	<u>105° 19' 50"</u>	<u>above standpt.</u>
<u>TRIG PLUG</u>	<u>19 42 40</u>	<u>6.165</u>	<u>1.333</u> above standpt.	<u>RO</u>	<u>0 00 00</u>	<u>105° 19' 50"</u>	<u>above standpt.</u>
<u>SSM</u>	<u>286 24 10</u>	<u>9.848</u>	<u>0.836</u> above standpt.	<u>D. Hole 305° 01' 40"</u>	<u>199 43 50</u>	<u>6.161</u>	<u>-1.328</u> below standpt.
<u>PLUG</u>	<u>125 03 30</u>		<u>above standpt.</u>	<u>SSM 0° 34' 00"</u>	<u>255 19 10</u>	<u>11.920</u>	<u>0.448</u> below standpt.
	<u>31 45 20</u>		<u>above standpt.</u>				<u>above standpt.</u>
			<u>above standpt.</u>				<u>above standpt.</u>

Prepared by:.....

Checked:.....

Noted on U.T.M. Card

TS 1215

STATION ~~HGRADATE~~ BUDGERY

Owner's Name: MARK GRIMMOND

Address: "Rockview"

HERMIDALE

Phone: 068 330 711

Current Occupant:

Address:

Phone: .

ACCESS

1 HR from NYNGBAN

Access Report of ~~22~~ 7/19/94 was found suitable/unsuitable. 4WD JULY '94

Access Report of ~~22~~ 7/19/94 was found suitable/unsuitable.

0.0 Hermidale Hotel head towards Wilcannia, Cobbar


1.8 Turn R "White Rock Rd"

3.1 Turn L gateway "Rockview"

4.0 Turn L about 100 mts before white Telecom post (Homestead straight ahead)

4.1 Veer L and make own way

4.25 Veer L across saddle and make own way up hill

4.45 BUDGERY 

This section to be completed by officer: constructing pillar.

Original station mark found/not found.

Description of mark:

Original beacon found/not found.

Description of beacon:

Height: Top of Vanes to Top Mark.....m.

Height of mark.....m.	above	rock/conc.....m.	above
	below		below

Diameter of Vanesft.
Height of Cairnm.

Original Beacon has/has not been destroyed by me.

Record of Station