

CENTRAL MAPPING AUTHORITY

GEODETTIC SURVEY OF N.S.W.

GEODETTIC STATION RECONNAISSANCE and MAINTENANCE REPORT

Description:

Note: Cross out word or words which do not apply

1. Cleared by James bearing Not cleared from Trig. Mast
2. Mast & Vanes have been painted white & black respectively.
3. The station/pillar was unpiled/not unpiled/constructed on 19 dimensions now being:
 - Description of mark should be explicitly e.g., S/Steel Pillar Plate, Steel plug, Brass plug, Bolt, G.I. Pipe
 - Height of mark above rock/concrete/ below G.L.
 - Height of Top Vanes to Top Mark/Pillar plate above below m. Diameter of Vanes (vertical) above below m.
 - Height of Cairn above below m. Diameter of Cairn above below m. Name Plate found/not found/placed.
 - Length of Mast above below m. (approximate if not unpiled)
4. A set in conc/rock has been placed/found, bearing °M from Mast/Plug/Pillar
5. A set in conc/rock has been placed/found, bearing °M from Mast/Plug/Pillar
6. A set in conc/rock has been placed/found, bearing °M from Mast/Plug/Pillar
7. A set in conc/rock has been placed/found, bearing °M from Mast/Plug/Pillar
8. Action required: Location of mark - clearing if point is to be used.

STANDPOINT: Top of hill - no mark found.

Mark	Direction	Horiz. Distance	Height Difference	Mark	Direction	Horiz. Distance	Height Difference
WYERA 487S	67°M		Visible if 3m	Height of instrument			above standpt.
MARBARUDGILL 333Z	129°M		Visible if cleared both ends				above standpt.
WYALBANK 486S	141°M		May be visible				above standpt.
Silo	151°M		Through trees				above standpt.
MULGA 5553	223°M		Not on				above standpt.
LULAH 2909			Heavily timbered hill only visible				above standpt.
BILLYS LOOKOUT 390	23°M		Intervening timber on ridge 12k				above standpt.

Prepared by: J. C. Robins

Noted on U.T.M. Card

S: 2733-1

STATION: **SPY** No.: **4154**

MAP SHEET SCALE 1:250 000 **FORBES**

INSPECTED BY: **J. Robins** DATE: **20/1/81**

AUTHORITY: **C.M.A** FIELD BOOK: **AB 01903**

Station Diagram

North

Not to Scale

Site has been quarried.

No mark or remains found

2: 2733-2 D. West, Government Printer

Beacon Diagram <div style="border: 1px solid black; width: 100%; height: 100%; display: flex; align-items: center; justify-content: center; text-align: center;"> Not beacons. </div>	Net to Scale <div style="border: 1px solid black; width: 100%; height: 100%; display: flex; align-items: center; justify-content: center;"> </div>	STATION SPY IS 4154	Owner's Name: Current Occupant: Address: Address: Phone: Phone: ACCESS 20/1/1981 Access Report of/19 was found suitable/unsuitable. km West Wyalong P.O. - head west on Newell/Mid-western Hwy. 0.44 Pass Newell Hwy turn off to left - head straight on towards the 0.60 Turn right SP Lake Cargelligo & Condobolin. 1.06 Cross Rlyway at level crossing 6.4 Bridge over Gogies Creek (SP Tea Tree Creek) under construction at time of survey 8.25 At top of ridge turn left off road to make own way to top of small rocky rise - timbered. NO MARK FOUND - Hill has been quarried - resection may not be possible due to clearing required at other trig. Line to Billys Lookout is possibly not on - ridge north of SPY in Vanses. Hill easy to clear for 360° but little value unless mark is located.
			Date Record of Station

This section to be completed by officer constructing pillar.

Original station mark found/not found.

Description of mark:

Original beacon found/not found.

Description of beacon:

Height Top of Vanses to Top Mark m.

Height of mark m. above G.L. below

Diameter of Vanses m. Height of Cairn m.

Original Beacon has/has not been destroyed by me.