	Inguinalication survey of 11.5.14.		
Department of Lands	RECONNAISSANCE and MAINTENANCE REPORT	STATION BALFOUR	JR 702
This Trig. Station has been:-	Note: Cross out word or words which do not apply	Co:	Ph:
		Map Sheet:	No:
1. Completely cleared to permit 360° vision to surrounding Trigs.	unding Trigs.	Inspected by:	Date:
2. Cleared by lanes bearing	from Trig. Mast	Authority	Field Book:
3. Trig. Mast & Vanes have been painted white & black respectively.	ack respectively.	Beacon Diagram	Not to Scale
4. The Trig. was unpiled/not unpiled, dimensions now being: $\sum_{i=1}^{n}$	w being: "Dyrgian	Recommended for	for relegation
Description of mark	should be explicit, e.g. Steel plug, Brass plug, Bolt, G.I. Pipe		2
Height of mark	ock/concretem above G.L.		
Height of Top Vanes to Top Mark m.	Diamete		
Height of Cairn	Diameter of Cairnm.	See MAYS	HILL report
Length of Mast	(approximate if not unpiled)	12	
5. Aset in conc/rock has been placedm. bearing			
6. Am. set in conc/soil has been placedm. bearing			
7. A bearing			
8. A			
9. Connectionm. toto	saring		
10. Connectiontototo	: m. bearing		
11. Connectiontototo	aring	Date Rec	Record of Station
12. Connectiontoto	: m. bearing		
13. Diff. Htisis	ove Jow		
14. Diff. Htisis	ove Jave		
15. Djff. Hı	dbove		
16. Diff. Htisis.	uerow cbove		
0		Charlerd	

TS702 | Print Date: 31/05/2022 15:09 | No Of Pages: 2 | Property of DFSI – Spatial Services 1

- -

