

CENTRAL MAPPING AUTHORITY

GEODETIC SURVEY OF M.S.W.

GEODETIC STATION RECONNAISSANCE and MAINTENANCE REPORT

Description:

1. Cleared by lanes bearing $300^{\circ} 4' 35''$ \rightarrow $145^{\circ} 2'$ Note: Cross out word or words which do not apply
2. Mast & Vanes have been painted white & black respectively. \checkmark from Trig. Mast
3. The station ~~marker~~ was ~~unplaced~~/not unplaced/~~conspicuous~~ on 7.8 \rightarrow 19.80 , dimensions now being:
 - Description of mark..... should be explicit, e.g., S/Steel Pillar Plate, Steel plug, Brass plug, Bolt, G.I. Pipe
 - Height of mark..... ^{above} rock/concrete; Mark is.....m. ^{above} below G.L.
 - Height of Top Vanes to Top Mark/Pillar plate.....m. Diameter of Vanes (vertical).....m. 0.765 \checkmark
 - Height of Cairn.....m. Diameter of Cairn.....m. Name Plate ~~found~~/not ~~found~~/placed.
 - Length of Mast.....m. (approximate if not unplaced) 3.765
4. A.....set in conc/rock has been placed/found, bearing.....°M from Mast/Plug/Pillar
5. A.....set in conc/rock has been placed/found, bearing.....°M from Mast/Plug/Pillar
6. A.....set in conc/rock has been placed/found, bearing.....°M from Mast/Plug/Pillar
7. A.....set in conc/rock has been placed/found, bearing.....°M from Mast/Plug/Pillar
8. Action required: *to be fixed & capped*

STANDPOINT:

Mark	Direction	Horiz. Distance	Height Difference	Mark	Direction	Horiz. Distance	Height Difference
			above standpt.				above standpt.
			below standpt.				below standpt.
			above standpt.				above standpt.
			below standpt.				below standpt.
			above standpt.				above standpt.
			below standpt.				below standpt.
			above standpt.				above standpt.
			below standpt.				below standpt.
			above standpt.				above standpt.
			below standpt.				below standpt.

Prepared by:

Checked: *[Signature]* Noted on U.T.M. Card

Sr: 2733-1

STATION: *BENDICK GS.* No.: *853*

MAP SHEET SCALE 1:250 000 *Strollburn*

INSPECTED BY: *P. HORTS.* DATE: *7.8.60*

AUTHORITY: *C.M.A.* FIELD BOOK: *1688*

STATION BENDICK 853	Owner's Name: MA J REIN Address: HILLSIDE Phone: BENDICK MURRELL 83-2220	Owner's Name: MA J DILLY Address: HILLSIDE Phone: BENDICK MURRELL 83-2220	ACCESS Access Report of 7.1.8/1988 was found suitable/unsuitable. 1m. LEPTURK 0.00 v. P.O. KARUNATHA HEADS TOWARDS YOUNG. 0.10. TURN LEFT ONTO OUTRICK WAY AND HEAD TOWARDS YOUNG 200. MABIL ROADHOUSE ON RIGHT (CRANFATHER) 6.30. TURN LEFT KAROO PA LEAVE 12.0. TURN RIGHT - IRON GATE (LOCAL) KEY IS UNDER ROCK IN A TIN 500 FEET CLIMB NORTH. SOUTH FENCE. 12.30. KEEP LEFT TO FOOT OF HILL - A SBR RUNNING TO TOP OF RIDGE IS VISIBLE - MAKE OWN WAY TO FENCE 12.00. AT FENCE - LEAVE VEHICLE HERE AND ABOUT 25 MINUTES TO TOP WHEN ABOUT 300 METRES ALONG TOP TO TRIG
Beacon Diagram 	Not to Scale	This section to be completed by officer constructing pillar. Original station mark found/not found. Description of mark: Original beacon found/not found. Description of beacon: Height Top of Vanes to Top Markm. Height of markm. above G.L. below Diameter of Vanesm. Height of Cairnm. Original Beacon has/has not been destroyed by me.	Date Record of Station