

CENTRAL MAPPING AUTHORITY

GEODETIC SURVEY OF M.S.W.
 GEODETIC STATION RECONNAISSANCE and MAINTENANCE REPORT


STATION: BREMER No.: 1155
 MAP SHEET SCALE 1:250 000 CARGELLIGO
 INSPECTED BY: G. C. HANNA DATE: 19/5/79
 AUTHORITY: C. M. A. FIELD BOOK:


- Description:
1. Cleared by lanes bearing..... from Trig. Mast
 2. Mast & Vanes have been painted white & black respectively.
 3. The station/pillar was unpiled/not unpiled/constructed on..... 19..... dimensions now being:
 Description of mark..... should be explicit, e.g., S/Steel Pillar Plate-Steel plug, Brass plug, Bolt, G.I. Pipe
 Height of mark.....m. above rock/concrete; Mark is.....m. above G.L.
 Height of Top Vanes to Top Mark/Pillar plate.....m. Diameter of Vanes (vertical).....m.
 Height of Cairn.....m. Diameter of Cairn.....m. Name Plate found/not found/placed.
 Length of Mast.....m. (approximate if not unpiled)
 4. A..... set in conc/rock has been placed/found, bearing.....° M from Mast/Plug/Pillar
 5. A..... set in conc/rock has been placed/found, bearing.....° M from Mast/Plug/Pillar
 6. A..... set in conc/rock has been placed/found, bearing.....° M from Mast/Plug/Pillar
 7. A..... set in conc/rock has been placed/found, bearing.....° M from Mast/Plug/Pillar
 8. Action required:.....

STANDPOINT:

Mark	Direction	Horiz. Distance	Height Difference	Mark	Direction	Horiz. Distance	Height Difference
			above standpt.				above standpt.
			below				below
			above standpt.				above standpt.
			below				below
			above standpt.				above standpt.
			below				below
			above standpt.				above standpt.
			below				below
			above standpt.				above standpt.
			below				below
			above standpt.				above standpt.
			below				below

Prepared by: G. Hanna 21/5/79 Checked: Noted on U.T.M. Card



St 2733-2 D, West, Government Printer	STATION BREWER 1155	<p> Owner's Name: K. J. Rose Address: Carlisle # Phone: Monia Grap Bunda 67 5325 </p> <p> Current Occupant: Address: Phone: </p> <p> ACCESS See Langtree 3030-N </p> <p> Access Report of 11/5/1979 was found suitable/unsuitable. </p> <p> Cairn, mast & vanes confirmed by owner, who has visited the trig within the last 12 months. </p> <p> Light clearing is required. 20 minute walk to trig. </p>
Beacon Diagram		<p style="text-align: right;">Not to Scale</p> 
This section to be completed by officer constructing pillar.		
Original station mark found/not found.		
Description of mark:		
Original beacon found/not found.		
Description of beacon:		
Height Top of Vanes to Top Mark: m.		
Height of mark: m. above rock/conc. m. above G.L. below		
Diameter of Vanes: m. Height of Cairn m.		
Original Beacon has/has not been destroyed by me.		
		Date
		Record of Station