


CENTRAL MAPPING AUTHORITY

GEODETIC SURVEY OF NSW

GEODETIC STATION RECONNAISSANCE and MAINTENANCE REPORT

STATION: <b>BROUGHTON</b>	No.: <b>1180</b>
MAP SHEET SCALE 1:250 000	<b>Wollongong</b>
INSPECTED BY: <b>A. Sivertsen</b>	DATE: <b>11-1-79</b>
AUTHORITY: <b>CMA</b>	FIELD BOOK: <b>1723</b>



**KANGAROO VALLEY**  
1:25,000

8. Action required:

STANDPOINT:		STANDPOINT:		STANDPOINT:		STANDPOINT:	
Mark	Direction	Horiz. Distance	Height Difference	Mark	Direction	Horiz. Distance	Height Difference
			above standpt.				above standpt.
			below standpt.				below standpt.
			above standpt.				above standpt.
			below standpt.				below standpt.
			above standpt.				above standpt.
			below standpt.				below standpt.
			above standpt.				above standpt.
			below standpt.				below standpt.
			above standpt.				above standpt.
			below standpt.				below standpt.

Station Diagram  
North  
Not to Scale

Attempted to climb up eastern end of hill but cliffs were too high (Same way as original P.O. went)

It is possible to drive around to southern side & may be possible to climb up here.

Would be a 1-2 hour walk

+


Prepared by: *[Signature]* 23-1

Checked: *[Signature]*

Noted on U.T.M. Card

Checked

St 2735-4 D. West, Government Printer

Beacon Diagram 	Not to Scale	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 50%; padding: 5px;">                             STATION <b>BROUGHTON</b> 1180                               Owner's Name: In <b>RODWAY NATURE RESERVE</b>                              Address: <b>(Pt Macken National Park)</b>                               Phone: .....                               Access Report of <b>11/1/1979</b> was found suitable/unsuitable.                         </td> <td style="width: 50%; padding: 5px;">                             Current Occupant: .....                              Address: .....                               Phone: .....                               ACCESS                         </td> </tr> </table>	STATION <b>BROUGHTON</b> 1180  Owner's Name: In <b>RODWAY NATURE RESERVE</b> Address: <b>(Pt Macken National Park)</b>  Phone: .....  Access Report of <b>11/1/1979</b> was found suitable/unsuitable.	Current Occupant: ..... Address: .....  Phone: .....  ACCESS
STATION <b>BROUGHTON</b> 1180  Owner's Name: In <b>RODWAY NATURE RESERVE</b> Address: <b>(Pt Macken National Park)</b>  Phone: .....  Access Report of <b>11/1/1979</b> was found suitable/unsuitable.	Current Occupant: ..... Address: .....  Phone: .....  ACCESS			
This section to be completed by officer constructing pillar. Original station mark found/not found.		Date ..... Name of Station .....		
Description of mark: ..... Original beacon found/not found.		Height Top of Vases to Top Mark .....m. Height of mark .....m. above G.L. Diameter of Vases .....m. below Height of Cairn .....m.		
Description of beacon: ..... Original Beacon has/has not been destroyed by me.		Date ..... Name of Station .....		