

TS 10

Department of Lands

Integral Survey of N.S.W.

RECONNAISSANCE and MAINTENANCE REPORT

STATION HORNSBY HEIGHTS (P)

This Trig. Station has been:-

Note: Cross out word or words which do not apply

1. Completely cleared to permit 360° vision to surrounding Trigs.

2. Cleared by limes bearing: from Trig. Mast

Co: _____ Ph: _____
 Map Sheet: _____ No: _____
 Inspected by: _____ Date: _____
 Authority: _____ Field Book: _____

STATION HORNSBY HTS (RES) or
~~HORNSBY HTS (RES)~~

FEET

STATION	DATE	HEIGHTS	REMARKS
775.53		236.38	
773.53		235.77	
769.83		234.55	
767.26		233.99	
763.01		232.56	
		17.50	
		17.74	

Leveling bar: N.P. 18 (10.3.23) -
 3.12 1933
 D. 174

G 38

14. Diff. Ht. is m. above / below
15. Diff. Ht. is m. above / below
16. Diff. Ht. is m. above / below

Prepared by: _____ Checked: _____

Date	Record of Station

Beacon Diagram Not to Scale

