

CENTRAL MAPPING AUTHORITY

GEODETIC SURVEY OF N.S.W.

GEODETIC STATION RECONNAISSANCE and MAINTENANCE REPORT

Description:

1. Cleared by lanes bearing... *CLEAR LINES TO BUNEN 25 135 04*..... from Trig. Mast
2. Mast & Vanes have been painted white & black respectively.
3. The station ~~marker~~ was unpiled/~~replaced~~ on *15 DEC 1984*, dimensions now being:
Description of mark *Steel Plug, Steel Plate, Steel plug, Brass plug, Bolt, G.I. Pipe*

Height of mark *6.050* m. ^{above} rock/~~concrete~~; Mark is ^{above} G.L.
 Height of Top Vanes to Top Mark *3.715* m. Diameter of Vanes (vertical)..... *0.610* m.
 Height of Cairn *1.300* m. Diameter of Cairn *0.000* m. Name Plate found/not found/placed.
 Length of Mast *3.765* m. (approximate if not unpiled)

4. A..... set in conc/rock has been placed/found, bearing..... °M from Mast/Plug/Pillar
5. A..... set in conc/rock has been placed/found, bearing..... °M from Mast/Plug/Pillar
6. A..... set in conc/rock has been placed/found, bearing..... °M from Mast/Plug/Pillar
7. A..... set in conc/rock has been placed/found, bearing..... °M from Mast/Plug/Pillar

8. Action required: *SATELITE MARKS ALSO. PAKE CONCRETE PILLAR*

STANDPOINT:

Mark	Direction	Horiz. Distance	Height Difference	Mark	Direction	Horiz. Distance	Height Difference
			above standpt				above standpt
			below				below
			above standpt				above standpt
			below				below
			above standpt				above standpt
			below				below
			above standpt				above standpt
			below				below
			above standpt				above standpt
			below				below
			above standpt				above standpt
			below				below

Prepared by: *P. Potts* 12.12.84 Checked: *P.S. 10/1/85* Noted on U.T.M. Card *41*

STATION: *CADJAN MARY ST.* No.: *1343*
 MAP SHEETS SCALE 1:250 000 *BEB-A*
 INSPECTED BY: *P. Potts* DATE: *10.12.84*
 AUTHORITY: *C.M.A* FIELD BOOK:

Station Diagram

Not to Scale

PLEASE NOTE
TRIG UNPILED & LEFT UNPILED
& MARKED BY PART OF OLD
MAST.
MAST & VANES HAVE BEEN
DESTROYED BY ME.

Checked *10/1/85*

