

LAND INFORMATION CENTRE

GEODETTIC SURVEY OF A.S.M.

GEODETTIC STATION RECONNAISSANCE and MAINTENANCE REPORT

STATION: **CHOY** No.: **1476**
 MAP SHEET SCALE 1:250,000 **BARNATO SH/55-13**
 INSPECTED BY: **C. Zahra** DATE: **24-7-94**
 AUTHORITY: **LIC** FIELD BOOK: **—**

Description: **View is obstructed by small trees**
 Note: Cross out word or words which do not apply
 Cleared by James bearing from Trig. Mast

1. Mast & Vanes have been painted white & black respectively.

2. The station/pillar was ~~erected~~ not unpiled/constructed on 19....., dimensions now being:

Description of mark..... should be explicit, e.g., S/Steel Pillar, Plate, Steel plug, Brass plug, Bolt, G.I. Pipe

Height of mark.....m. above rock/concrete; Mark is.....m. above G.L. (in good order)

Height of Top Vanes to Top Mark/Pillar plate.....m. Diameter of Vanes (vertical) 0.76.....m.

Height of Cairn 1-6.....m. Diameter of Cairn 1-3.....m. Name Plate ~~found~~/not found/pieces.

Length of Mast.....m. (approximate if not unpiled)

4. A. **SSM plaque** set in ~~conc~~/rock has been ~~placed~~ found, bearing.....°M from Mast/~~Plug~~Pillar, **approx 3m**

5. A..... set in conc/rock has been placed/found, bearing.....°M from Mast/Plug/Pillar

6. A..... set in conc/rock has been placed/found, bearing.....°M from Mast/Plug/Pillar

7. A..... set in conc/rock has been placed/found, bearing.....°M from Mast/Plug/Pillar

8. Action required: **Paint M & V connections**

STANDPOINT:				STANDPOINT:			
Mark	Direction	Horiz. Distance	Height Difference	Mark	Direction	Horiz. Distance	Height Difference
			above standpt.				above standpt.
			below				below
			above standpt.				above standpt.
			below				below
			above standpt.				above standpt.
			below				below
			above standpt.				above standpt.
			below				below
			above standpt.				above standpt.
			below				below

Prepared by: *M. Jam* Checked: *Checked* Noted on: U.T.M. Card

St 2733-2 D. West, Government Printer

STATION CHDY TS 1476	Owner's Name: Trig Reserve within Mt Grenfell Nat. Park Current Occupant: Address: Phone: ACCESS 24-7-1994 Phone: Prev. Access Report of 146 was found settible/unsuitable, NA.								
Beacon Diagram Not to Scale	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 10%; text-align: center;">D.O km</td> <td style="width: 10%; text-align: center;">40.0</td> <td style="width: 10%; text-align: center;">71.0</td> <td style="width: 10%; text-align: center;">72.0</td> <td style="width: 60%;"> From Lebar take Wilcannia Rd Turn R (SP: PULPULLA SO), Gravel rd Turn R (SP: Mt Grenfell Historic site), gravel rd. Parking area. Walk 300m to last aboriginal art site, continue along 'NGIYAMBAA WALKABOUT' trail (abt 3 km, marked trail, easy walk) </td> </tr> </table>	D.O km	40.0	71.0	72.0	From Lebar take Wilcannia Rd Turn R (SP: PULPULLA SO), Gravel rd Turn R (SP: Mt Grenfell Historic site), gravel rd. Parking area. Walk 300m to last aboriginal art site, continue along 'NGIYAMBAA WALKABOUT' trail (abt 3 km, marked trail, easy walk)			
D.O km	40.0	71.0	72.0	From Lebar take Wilcannia Rd Turn R (SP: PULPULLA SO), Gravel rd Turn R (SP: Mt Grenfell Historic site), gravel rd. Parking area. Walk 300m to last aboriginal art site, continue along 'NGIYAMBAA WALKABOUT' trail (abt 3 km, marked trail, easy walk)					
	This section to be completed by officer constructing pillar. Original station mark found/not found. Description of mark: Original beacon found/not found. Description of beacon: Height Top of Vanes to Top Mark.....m. Height of mark.....m. above G.L. below Diameter of Vanesm. Height of Cairn.....m. Original Beacon has/has not been destroyed by me.								
	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 10%; text-align: center;">Date</td> <td style="width: 90%;">Record of Station</td> </tr> <tr> <td> </td> <td> </td> </tr> <tr> <td> </td> <td> </td> </tr> <tr> <td> </td> <td> </td> </tr> </table>	Date	Record of Station						
Date	Record of Station								