

GEODETTIC SURVEY OF N.S.W.

CENTRAL MAPPING AUTHORITY

GEODETTIC STATION RECONNAISSANCE and MAINTENANCE REPORT

Description:

Note: Cross out word or words which do not apply

1. Cleared by lanes bearing.....
2. Mast & Vanes have been painted white & black respectively, found in cairn of rocks
3. The station/pillar was applied/not unpiled/constructed on.....m. ~~dimensions~~ ~~new~~ being:
 - Description of mark.....should be explicit, e.g., S/Steel Pillar Plate, Steel plug, Brass plug, Bolt, G.I. Pipe
 - Height of mark.....m. ^{above} rock/concrete; Mark is.....m. ^{above} _{below} G.L.
 - Height of Top Vanes to Top Mark/Pillar platem. Diameter of Vanes (vertical).....m.
 - Height of Cairn.....m. Diameter of Cairn.....m. Name Plate found/not found/placed.
 - Length of Mast.....m. (approximate if not unpiled)
4. A.....set in conc/rock has been placed/ found, bearing.....°M from Mast/Plug/Pillar
5. A.....set in conc/rock has been placed/ found, bearing.....°M from Mast/Plug/Pillar
6. A.....set in conc/rock has been placed/ found, bearing.....°M from Mast/Plug/Pillar
7. A.....set in conc/rock has been placed/ found, bearing.....°M from Mast/Plug/Pillar
8. Action required: *Station strike to 3 days clearing required*

STANDPOINT:

Mark	Direction	Horiz. Distance	Height Difference	Mark	Direction	Horiz. Distance	Height Difference
			above standpt				above standpt
			below				below
			above standpt				above standpt
			below				below
			above standpt				above standpt
			below				below
			above standpt				above standpt
			below				below
			above standpt				above standpt
			below				below

Prepared by: *P.L. Bamola 14/5/22* Checked: *Checked*

SI 2753-1

Noted on U.T.M. Card

STATION: *Coghill* No.: *1529*

MAP SHEET SCALE 1:250 000 *Canberra*

INSPECTED BY: *P.L. Bamola* DATE: *May 1979*

AUTHORITY: *CMA* FIELD BOOK:

