

CENTRAL MAPPING AUTHORITY

GEODETIC SURVEY OF N.S.W.  
 GEODETIC STATION RECONNAISSANCE and MAINTENANCE REPORT

STATION: **COLINTON GS** No.: **1532**  
 MAP SHEET SCALE 1:250 000 **CANBERRA**  
 INSPECTED BY: **W MILLER** DATE: **1-2-79**  
 AUTHORITY: **CWA** FIELD BOOK:

Description:  
 Note: Cross out word or words which do not apply

- Cleared by lances bearing..... ~~S. AINSWORTH~~..... **T. MILLER**..... from Trig, Mast
- Mast & Vanes have been painted white & black respectively.
- The station/~~marker~~ was ~~unplaced~~/not unplaced/~~observed~~ on..... **1-7-79**..... **19-7-79**, dimensions now being:  
 Description of mark..... should be explicit, e.g., S/Steel Pillar Plate, Steel plug, Brass plug, Bolt, G.I. Pipe  
 Height of mark.....m. <sup>above</sup> rock/concrete; Mark is.....m. <sup>above</sup> G.L.
- Height of Top Vanes to Top Mark/Pillar plate .....m. Diameter of Vanes (vertical).....m.  
 Height of Cairn.....m. Diameter of Cairn.....m. Name Plate found/not found/placed.  
 Length of Mast..... **3.8**.....m. (approximate if not unplaced)
- A.....set in conc./rock has been placed/found, bearing.....° M from Mast/Plug/Pillar
- A.....set in conc./rock has been placed/found, bearing.....° M from Mast/Plug/Pillar
- A.....set in conc./rock has been placed/found, bearing.....° M from Mast/Plug/Pillar
- A.....set in conc./rock has been placed/found, bearing.....° M from Mast/Plug/Pillar

STANDPOINT:

Mark	Direction	Horiz. Distance	Height Difference	Mark	Direction	Horiz. Distance	Height Difference
			above standpt.				above standpt.
			below				below
			above standpt.				above standpt.
			below				below
			above standpt.				above standpt.
			below				below
			above standpt.				above standpt.
			below				below
			above standpt.				above standpt.
			below				below

Prepared by: **W Miller** 23-2-79 Checked: **Checked**  
 Noted on U.T.M. Cart

GS 24

STATION COLINTON IS 1532	
<p>Owner's Name: "NEIKAH"                      Address: "NEIKAH"                      Phone: "Colingwood"</p> <p>Current Occupant:                      Address:                      Phone: "Colingwood"</p> <p>ACCESS                      Access Report of 1.2.19.79 was found suitable/unavailable.</p>	<p style="text-align: center;">Scale 1:25000 Ask directions from owner at "Neikah"</p> <p>Date: 1.2.79                      Record of Station: Disited                      Breddo 9km</p>
<p>Not to Scale</p> <p>This section to be completed by officer constructing pillar.</p> <p>Original station mark found/not found.</p> <p>Description of mark: .....</p> <p>Original beacon found/not found.</p> <p>Description of beacon: .....</p> <p>Height Top of Vanes to Top Mark: .....m.                      above rock/cont .....m. below G.L.</p> <p>Height of mark: .....m.                      above rock/cont .....m. below</p> <p>Diameter of Vanes .....m. Height of Cairn .....m.</p> <p>Original Beacon has/has not been destroyed by me.</p>	