

CENTRAL MAPPING AUTHORITY

GEODETIC SURVEY OF MSW

GEODETIC STATION RECONNAISSANCE and MAINTENANCE REPORT

Description:

1. Cleared by lens - bearing Note: Cross out word or words which do not apply from - Trig. Mast

2. Mast & Vanes have been painted white & black respectively.

3. The station/pillar was unplied/not unplied/constructed on 19 dimensions now being: *in ring of rocks by*

Description of mark should be explicit, e.g., *Steel Pillar-Plate, Steel plug, Brass plug, 304L G.I. Pipe*

Height of mark m. ^{above} rock/concrete; Mark is m. ^{above} G.L.

Height of Top Vanes to Top Mark/Pillar plate m. Diameter of Vanes (vertical) m.

Height of Cairn m. Diameter of Cairn m. Name Plate found/not found/placed.

Length of Mast m. (approximate if not unplied)

4. A set in conc/rock has been placed/found, bearing ° M from Mast/Plug/Pillar

5. A set in conc/rock has been placed/found, bearing ° M from Mast/Plug/Pillar

6. A set in conc/rock has been placed/found, bearing ° M from Mast/Plug/Pillar

7. A set in conc/rock has been placed/found, bearing ° M from Mast/Plug/Pillar

8. Action required: *Mark and vanes fallen over - needs replacing*

STANDPOINT:

Mark	Direction	Horiz. Distance	Height Difference	Mark	Direction	Horiz. Distance	Height Difference
			above standpt.				above standpt.
			below				below
			above standpt.				above standpt.
			below				below
			above standpt.				above standpt.
			below				below
			above standpt.				above standpt.
			below				below
			above standpt.				above standpt.
			below				below
			above standpt.				above standpt.
			below				below

Prepared by:

Checked:

Noted on U.T.M. Card

St 2733-1

Checked

STATION: DANIELS No.: 1777

MAP SHEET SCALE 1:250 000 CAN BERRA

INSPECTED BY: P. K. BAMOLA DATE: JUNE 1978

AUTHORITY: FIELD BOOK:

Not to Scale

St 2743-2 D. West, Government Printer

STATION

Daniel TS 1777

Beacon Diagram	Not to Scale

Owner's Name:
Current Occupant:
Address:
Address:
Phone:
Phone:
ACCESS
June 1978
Access Report of...../19.....was found suitable/unsuitable.

10 meters walk from sealed road. Refer
Ambrose 8627-1-5.

This section to be completed by officer constructing pillar.
Original station mark found/not found.
Description of mark:
Original beacon found/not found.
Description of beacon:
Height Top of Vanes to Top Markm.
Height of mark.....m. above G.L.
 below rock/conem. below
Diameter of Vanesm. Height of Cairnm.
Original Beacon has/has not been destroyed by me.

Date	Record of Station