

CENTRAL MAPPING AUTHORITY  
Department of Lands

Trigonometrical Survey of N.S.W.

RECONNAISSANCE and MAINTENANCE REPORT

This Trig. Station has been:-

Note: Cross out word or words which do not apply

1. Completely cleared to permit 360° vision to surrounding Trigs. ✓
2. Cleared by lanes bearing..... from Trig. Mast
3. Trig. Mast & Vanes have been painted white & black respectively.
4. The Trig. was unpiled/not unpiled, dimensions now being: .....

Description of mark..... should be explicit, e.g. Steel plug, Brass plug, Bolt, G.I. Pipe

Height of mark..... m above below rock/concrete ..... m above below G.L.

Height of Top Vanes to Top Mark..... m. Diameter of Vanes (vertical)..... m.

Height of Cairn..... m. Diameter of Cairn..... m.

Length of Mast..... m. (approximate if not unpiled)

5. A..... set in conc/rock has been placed..... m bearing..... °M from Trig. Mast
6. A..... set in conc/soil has been placed..... m bearing..... °M from Trig. Mast
7. A..... set in conc/soil has been placed..... m bearing..... °M from Trig. Mast
8. A..... set in conc/rock has been placed..... m bearing..... °M from Trig. Mast

9. Connection..... to..... m bearing..... °M

10. Connection..... to..... m bearing..... °M

11. Connection..... to..... m bearing..... °M

12. Connection..... to..... m bearing..... °M

13. Diff. Ht. .... is..... m. above below

14. Diff. Ht. .... is..... m. above below

15. Diff. Ht. .... is..... m. above below

16. Diff. Ht. .... is..... m. above below

Prepared by: ML Morrison

Checked: .....

Noted on U.T.M. Card

STATION FENTON | TS 2041

Co: FITZROY | Ph: FENTON

Map Sheet: DARRIGO | No: 9437

Inspected by: ML Morrison | Date: 28-7-77

Authority: ..... | Field Book: 1580

Beacon Diagram

Not to Scale



Date

Record of Station

CAIRN ONLY FD. NO OTHER MARKS. REVISION 20/11/06

Checked

