

CENTRAL MAPPING AUTHORITY

GEODETIC SURVEY OF M.S.W.  
 GEODETIC STATION RECONNAISSANCE and MAINTENANCE REPORT

Description:  
 1. Cleared by lanes bearing.....  
 Note: Cross out word or words which do not apply  
 from Trig. Mast

2. Mast & Vanes have been painted white & black respectively.  
 3. The station/pillar was unpiled/not unpiled/constructed on.....19..... dimensions now being:

Description of mark.....should be explicit, e.g., S/Steel Pillar Plate, Steel plug, Brass plug, Bolt, G.I. Pipe  
 Height of mark.....m.....<sup>above</sup> rock/concrete; Mark is.....m.....<sup>above</sup> G.L.  
 Height of Top Vanes to Top Mark/Pillar plate.....m. Diameter of Vanes (vertical).....m.

Height of Cairn.....m. Diameter of Cairn.....m. Name Plate found/not found/placed.  
 Length of Mast.....m. (approximate if not unpiled)

- 4. A.....set in conc/rock has been placed/found, bearing.....°M from Mast/Plug/Pillar
- 5. A.....set in conc/rock has been placed/found, bearing.....°M from Mast/Plug/Pillar
- 6. A.....set in conc/rock has been placed/found, bearing.....°M from Mast/Plug/Pillar
- 7. A.....set in conc/rock has been placed/found, bearing.....°M from Mast/Plug/Pillar

8. Action required:.....  
 STATION NO. 227

STANDPOINT:			
Mark	Direction	Horiz. Distance	Height Difference
			above standpt.
			below standpt.
			above standpt.
			below standpt.
			above standpt.
			below standpt.
			above standpt.
			below standpt.
			above standpt.
			below standpt.
			above standpt.
			below standpt.

Prepared by: S. G. G. Not. Checked: y. G. G. 17 Noted on U.T.M. Card

St 227a-1

STATION: IVORY TS No.: 2572  
 MAP SHEET SCALE 1:250 000 SYDNEY  
 INSPECTED BY: G. JONES DATE: 22-4-80  
 AUTHORITY: CMA FIELD BOOK: Q1880

Station Diagram  
 North  
 Not to Scale

TRIG HAS VIEWS TO EAST ONLY.

+

Evidence of  
 old clearing  
 No marks found  
 Hence signed.

Checked

