

CENTRAL MAPPING AUTHORITY

GEODETIC SURVEY OF A.S.W.

GEODETIC STATION RECONNAISSANCE and MAINTENANCE REPORT

Description:

- Cleared by lanes bearing.....
Note: Cross out word or words which do not apply
- ~~Mast & Vanes have been painted white & black respectively.~~
- The station/pillar was unpiled/not unpiled/constructed on..... 19....., dimensions now being:
Description of mark..... should be explicit, e.g., S/Steel Pillar Plate, Steel plug, Brass plug, Bolt, G.I. Pipe
Height of mark.....m. ^{above} _{below} rock/concrete; Mark is.....m. ^{above} _{below} G.L.
Height of Top Vanes to Top Mark/Pillar plate.....m. Diameter of Vanes (vertical).....m.
Height of Cairn.....m. Diameter of Cairn.....m. Name Plate found/not found/placed.
Length of Mast.....m. (approximate if not unpiled)
- A..... ~~G.I. pipe~~..... set in ~~conc/rock~~ has been ~~placed~~/found, bearing..... ^{to} 188.°M ~~from Mast/Plug/Pillar~~
- A..... ~~S.S.M.~~..... set in ~~conc/rock~~ has been ~~placed~~/found, bearing..... ^{to} 43.°M ~~from Mast/Plug/Pillar~~
- A..... set in conc/rock has been placed/found, bearing.....°M from Mast/Plug/Pillar
- A..... set in conc/rock has been placed/found, bearing.....°M from Mast/Plug/Pillar
- Action required: ~~Needs painting black and white~~..... ~~needs clearing 36.0°~~.....

STATION: **KYBEYAN** No.: **2773**
 MAP SHEET SCALE 1:250 000 **BEGA**
 INSPECTED BY: **G. KEEP** DATE: **13/8/80**
 AUTHORITY: **C.M.A.** FIELD BOOK:

STANDPOINT:

Mark	Direction	Horiz. Distance	Height Difference	Mark	Direction	Horiz. Distance	Height Difference
			above standpt.				above standpt.
			below standpt.				below standpt.
			above standpt.				above standpt.
			below standpt.				below standpt.
			above standpt.				above standpt.
			below standpt.				below standpt.
			above standpt.				above standpt.
			below standpt.				below standpt.
			above standpt.				above standpt.
			below standpt.				below standpt.

Prepared by: *Jeffrey Keep 23/8/80* Checked: *William 12/9/80* Noted on U.T.M. Card *William 12/9/80*

# 2735-3 D. West. Government Printer Beacon Diagram	Not to Scale 	STATION KYBEYAN TS 2773 Owner's Name: Address: Phone: Current Occupant: Address: Phone: ACCESS Access Report of 11/12/1957 was found suitable/unsuitable. Wooden Mast, Tin Vanes and Cairn Cairn neatly stacked, Mast straight, Vanes in good condition
This section to be completed by officer constructing pillar. Original station mark found/not found. Description of mark: Original beacon found/not found. Description of beacon: Height Top of Vanes to Top Markm. Height of markm. above rock/conem. below G.L. Diameter of Vanesm. Height of Cairnm. Original Beacon has/has not been destroyed by me.		Date Record of Station