

GEODETTIC SURVEY OF A.S.I.K.

CENTRAL MAPPING AUTHORITY

GEODETTIC STATION RECONNAISSANCE and MAINTENANCE REPORT

Description:

- Cleared by lanes bearing *✓ DUSK GADWAN* *Note: Cross out word or words which do not apply* from Trig. Mast
- Mast & Vanes have been painted white & black respectively.
- The station/pillar was unpiled/not unpiled/constructed on .....19....., dimensions now being:  
Description of mark ..... should be explicit, e.g. S/Steel Pillar Plate, Steel plug, Brass plug, Bolt, G.I. Pipe  
Height of mark ..... m. <sup>above</sup> <sub>below</sub> rock/concrete; Mark is ..... m. <sup>above</sup> <sub>below</sub> G.L.  
Height of Top Vanes to Top Mark/Pillar plate ..... m. Diameter of Vanes (vertical) ..... m.  
Height of Cairn ..... m. Diameter of Cairn ..... m. Name Plate found/not found/placed.  
Length of Mast ..... m. (approximate if not unpiled)
- A ..... set in conc/rock has been placed/found, bearing ..... °M from Mast/Plug/Pillar
- A ..... set in conc/rock has been placed/found, bearing ..... °M from Mast/Plug/Pillar
- A ..... set in conc/rock has been placed/found, bearing ..... °M from Mast/Plug/Pillar
- A ..... set in conc/rock has been placed/found, bearing ..... °M from Mast/Plug/Pillar

8. Action required: *✓ MAST & VANES... IN POOR CONDITION... TAKE FURTHER ACTION*  
*STATION OVER GROW*

STANDPOINT:

Mark	Direction	Horiz. Distance	Height Difference	Mark	Direction	Horiz. Distance	Height Difference
			above standpt.				above standpt.
			below standpt.				below standpt.
			above standpt.				above standpt.
			below standpt.				below standpt.
			above standpt.				above standpt.
			below standpt.				below standpt.
			above standpt.				above standpt.
			below standpt.				below standpt.

Prepared by: *S. J. 6/2/89* *Checked: S. J. 27.4.89* *Noted on U.T.M. Grid*

Checked

STATION: *NARIRA* G.S. No.: *3328*  
 MAP SHEETS SCALE 1:250 000 *BEGA* SCALE 1:100 000  
 INSPECTED BY: *C. L. FORD* DATE: *4-2-89*  
 AUTHORITY: *C.M.A.* FIELD BOOK: *1949*

Station Diagram  
 Not to Scale  
 North

GS

\$12733 - 2 C. West Government Printer Beacon Diagram:	STATION <b>NARIRA GS TS 3328</b>	Owner's Name: <b>STATE FOREST</b> Address: Phone:	Current Occupant: Address: Phone:	ACCESS: Access Report of 4.12.1981 was found suitable/unsuitable. 0.00 / <b>COBARCO RD HEAD NORTH TOWARDS NARROUNA</b> 7.15 / <b>PASS "MANTLE HILL" PROPERTY ON RIGHT</b> 8.40 / <b>TURN OFF HWY ONTO FORESTY TRACK ON LEFT</b> <b>SP "BODALLA STATE FOREST"</b> 8.65 / <b>TAKE MAIN TRACK TO LEFT FOLLOW UP RIDGE</b> <b>PASSING SEVERAL TRACKS N &amp; S.</b> 12.15 / <b>T INTERSECTION TURN LEFT &amp; FOLLOW MAIN TRACK</b> <b>UP A LONG RIDGE LINE TO WEST</b> 17.15 / <b>ROAD BENDS TO RIGHT APPROX 200MTS BEFORE T INTERSECTION</b> <b>MAKE OWN WAY UP RIDGE ON LEFT ABOUT 200 METRES</b> <b>(FAINT TRACK NEEDS CLEARING)</b>
Not to Scale 		This section to be completed by officer constructing pillar. Original station mark found/not found. Description of mark: Original beacon found/not found. Description of beacon: Height Top of Varies to Top Mark .....m. Height of mark.....m. above rock/conc.....m. below G.L. Diameter of Varies .....m. Height of Cairn .....m. Original Beacon has/has not been destroyed by ma.		
		Date	Record of Station	