

GEODETTIC SURVEY OF N.S.W.

CENTRAL MAPPING AUTHORITY

GEODETTIC STATION RECONNAISSANCE and MAINTENANCE REPORT

Description:

Note: Cross out word or words which do not apply

1. Cleared by lanes bearing..... *Not checked*..... from Trig, Mast
2. Mast & Vanes have been painted white & black respectively.
3. The station/pillar was ~~unplaced~~ *constructed* on..... 19..... dimensions now being:
Description of mark..... should be explicit, e.g., S/Steel Pillar Plate, Steel plug, Brass plug, Bolt, G.I. Pipe
Height of mark..... m, ^{above}/_{below} rock/concrete; Mark is..... m, ^{above}/_{below} G.L.
Height of Top Vanes to Top Mark/Pillar plate m. Diameter of Vanes (vertical)..... m.
Height of Cairn..... 0.5 m. Diameter of Cairn..... l.m. ~~Name Plate found~~ *not found/placed*.
Length of Mast..... m. (approximate if not unplaced)
4. A..... set in conc/rock has been placed/found, bearing..... ° M from Mast/Plug/Pillar
5. A..... set in conc/rock has been placed/found, bearing..... ° M from Mast/Plug/Pillar
6. A..... set in conc/rock has been placed/found, bearing..... ° M from Mast/Plug/Pillar
7. A..... set in conc/rock has been placed/found, bearing..... ° M from Mast/Plug/Pillar
8. Action required:.....

STANDPOINT:

Mark	Direction	Horiz. Distance	Height Difference	Mark	Direction	Horiz. Distance	Height Difference
			above standpt				above standpt
			below standpt				below standpt
			above standpt				above standpt
			below standpt				below standpt
			above standpt				above standpt
			below standpt				below standpt
			above standpt				above standpt
			below standpt				below standpt
			above standpt				above standpt
			below standpt				below standpt

Prepared by: *W. Miller*

Checked: *W. Miller*

St 2738-1

Noted on U.T.M. Card

STATION: *NEALS TENT* No.: **3353**

MAP SHEET SCALE 1:250 000 *CANBERRA*

INSPECTED BY: *W MILLER* DATE: *12.5.78*

AUTHORITY: *CMA* FIELD BOOK:

Station Diagram

North

+ (crosshair)

Not to Scale

<p>81 2735-2 D. West, Government Printer</p>	<p>STATION NEALS TENT IS 3353</p>	<p>Owner's Name: Address: GARDLEIGH "homestead" Phone:</p> <p>Current Occupant: Address: Phone:</p> <p>ACCESS Access Report of 21.5.1978 was found suitable/unsuitable. Bunglelore.</p> <p>"The G6" See 1:25000 map when Printed</p>
<p>Beacon Diagram</p> <p style="text-align: right;">Not to Scale</p>	<p>This section to be completed by officer constructing pillar.</p> <p>Original station mark found/not found.</p> <p>Description of mark:</p> <p>Original beacon found/not found.</p> <p>Description of beacon:</p> <p>Height Top of Vanes to Top Markm.</p> <p>Height of markm. above G.L. below</p> <p>Diameter of Vanesm. Height of Cairnm.</p> <p>Original Beacon has/has not been destroyed by me.</p>	
<p>Date 12.5.78</p>		<p>Record of Station Visited - poor condition heavy timber</p>