

CENTRAL MAPPING AUTHORITY

GEODETIC SURVEY OF NSW

GEODETIC STATION RECONNAISSANCE and MAINTENANCE REPORT

Description:

1. Cleared by lanes bearing..... *Note: Cross out word or words which do not apply*
2. Mast & Vanes have been painted white & black respectively, from Trig. Mast
3. The station/pillar was unpiled/not unpiled/constructed on.....19....., dimensions now being:
 Description of mark.....should be explicit, e.g., S/Steel Pillar Plate, Steel plug, Brass plug, Bolt, G.I. Pipe
 Height of mark.....m. above below rock/concrete; Mark is.....m. above below G.L.
 Height of Top Vanes to Top Mark/Pillar platem. Diameter of Vanes (vertical).....m.
 Height of Cairn.....m. Diameter of Cairn.....m. Name Plate found/not found/placed.
 Length of Mastm. (approximate if not unpiled)
4. A.....set in conc/rock has been placed/found, bearing.....° M from Mast/Plug/Pillar
5. A.....set in conc/rock has been placed/found, bearing.....° M from Mast/Plug/Pillar
6. A.....set in conc/rock has been placed/found, bearing.....° M from Mast/Plug/Pillar
7. A.....set in conc/rock has been placed/found, bearing.....° M from Mast/Plug/Pillar
8. Action required:.....*Extensive searching needed. MARK APPROX. LOCATIONS FROM STATIONED*

STANDPOINT:

Mark	Direction	Horiz. Distance	Height Difference	Mark	Direction	Horiz. Distance	Height Difference
			above standpt. below				above standpt. below
			above standpt. below				above standpt. below
			above standpt. below				above standpt. below
			above standpt. below				above standpt. below
			above standpt. below				above standpt. below
			above standpt. below				above standpt. below
			above standpt. below				above standpt. below

Prepared by: R. COOK

Checked: *Not on U.T.M. Card*

Sr 2733-1

STATION: NMC 112 TS No.: 3450

MAP SHEET SCALE 1:250 000 NAKROMINE

INSPECTED BY: R. COOK DATE: SEPT 1978

AUTHORITY: NATIONAL MAPPING FIELD BOOK:

Station Diagram

North

North to Scale

Checked

Sr 2735-2 D. West, Government Printer

STATION **NM C 112. TS 3450**

Owner's Name: Address: Phone: Current Occupant: Address: Phone: Access Report of <u>Sept 1978</u> / 19..... was found suitable/unusable. Drive to (access) found on the Kenniwah 1:50,000 Sheet ACCESS	<p style="text-align: center;">Not to Scale</p> This section to be completed by officer constructing pillar. Original station mark found/not found. Description of mark: Original beacon found/not found. Description of Beacon: Height Top of Vanes to Top Markm. Height of markm <small>above rock/conc. below G.L.</small>m. Diameter of Vanesm. <small>Height of Cairnm.</small> Original Beacon has/has not been destroyed by me.
---	---

Date	SEPT. 1978	Revised of Station
	STATION VISITED IN CONNECTION WITH FIELD COMPLETION	