

CENTRAL MAPPING AUTHORITY

GEODETIC SURVEY OF NSW

GEODETIC STATION RECONNAISSANCE and MAINTENANCE REPORT

Description:

1. Cleared by lanes bearing.....
 Note: Cross out word or words which do not apply
 from Trig. Mast

2. Mast & Vanes have been painted white & black respectively.

3. The station/pillar ~~was~~ ^{is} ~~un~~ ^{re} ~~erected~~ ^{erected} /not unplaced/constructed on.....19....., dimensions now being:

Description of mark.....*C.P.D.*.....should be explicit. e.g., S/Steel Pillar Plate, Steel plug, Brass plug, Bolt, G.I. Pipe

Height of mark.....^{above} _{below} rock/concrete; Mark is.....^{above} _{below} G.L.

Height of Top Vanes to Top Mark/Pillar platem. Diameter of Vanes (vertical).....m.

Height of Cairn.....m. Diameter of Cairn.....m. Name Plate found/not found/placed.

Length of Mastm. (approximate if not unplaced)

4. A.....set in conc/rock has been placed/found, bearing.....° M from Mast/Plug/Pillar

5. A.....set in conc/rock has been placed/found, bearing.....° M from Mast/Plug/Pillar

6. A.....set in conc/rock has been placed/found, bearing.....° M from Mast/Plug/Pillar

7. A.....set in conc/rock has been placed/found, bearing.....° M from Mast/Plug/Pillar

8. Action required: *NO MAST. ARR. BASES. SARK. STALL. STAIRWAY. E. STAIRWAY. S. STAIRWAY. CRACKED.*

STANDPOINT:

STANDPOINT:

Mark	Direction	Horiz. Distance	Height Difference	Mark	Direction	Horiz. Distance	Height Difference
			above standpt.				above standpt.
			below				below
			above standpt.				above standpt.
			below				below
			above standpt.				above standpt.
			below				below
			above standpt.				above standpt.
			below				below
			above standpt.				above standpt.
			below				below
			above standpt.				above standpt.
			below				below

Prepared by: R. COOK

Checked: Noted on U.T.M. Card

SI 2733-1

STATION: TABRATONG G.S. No: 4252

MAP SHEET SCALE 1:250 000 NARROMINE

INSPECTED BY: R. COOK DATE: SEPT 1978

AUTHORITY: C.M.A. FIELD BOOK:

Station Diagram

North

Not to Scale

Checked

SI 2753-2 D. West, Government Printer

STATION **TABRATONG G.S. IS 4252**

Beacon Diagram	Not to Scale

Owner's Name:
 Address:
 Phone:

Current Occupant:
 Address:
 Phone:

Sept 1978
 ACCESS
 Access Report of/19.....was found suitable/unsuitable.

Drive to if a track is cleared through trees. Access found on the
 Kerriwah 1:50,000 sheet.

This section to be completed by officers constructing pillar.

Original station mark found/not found.
 Description of mark:
 Original beacon found/not found.
 Description of beacon:
 Height Top of Vanes to Top Markm.
 Height of markm. above rock/canem. above G.L.
 Diameter of Vanesm. below
 Height of Cairnm.
 Original Beacon has/has not been destroyed by me.

Date	Record of Station
1978 SEPT	STATION VISITED IN CONNECTION WITH FIELD COMPLETION