

CENTRAL MAPPING AUTHORITY

GEODETIC STATION RECONNAISSANCE and MAINTENANCE REPORT

STATION: **TAPITALEE NORTH** No: **4179**

MAP SHEET SCALE 1:250 000 **Wollongong**

INSPECTED BY: **A. Sivertsen** DATE: **11-1-79**

AUTHORITY: **CMA** FIELD BOOK: **1723**

- Description:
1. Cleared by lances bearing..... Note: Cross out word or words which do not apply
2. Mast & Vanes have been painted white & black respectively. from Trig. Mast
3. The station/pillar was unpiled/not unpiled/constructed on 19....., dimensions now being:
- Description of mark..... should be explicit, e.g., S/Steel Pillar Plate, Steel plug, Brass pdg, Bolt, G.I. Pipe
- Height of mark.....m. ^{above} rock/concrete; Mark is.....m. ^{above} G.L. _{below}
- Height of Top Vanes to Top Mark/Pillar platem. Diameter of Vanes (vertical).....m.
- Height of Cairn.....m. Diameter of Cairn.....m. Name Plate found/not found/placed.
- Length of Mastm. (approximate if not unpiled)
4. A.....set in conc/rock has been placed/found, bearing.....° M from Mast/Plug/Pillar
5. A.....set in conc/rock has been placed/found, bearing.....° M from Mast/Plug/Pillar
6. A.....set in conc/rock has been placed/found, bearing.....° M from Mast/Plug/Pillar
7. A.....set in conc/rock has been placed/found, bearing.....° M from Mast/Plug/Pillar
8. Action required:.....


BERRY
Stn. Top

STANDPOINT:		STANDPOINT:		STANDPOINT:		STANDPOINT:	
Mark	Direction	Horiz. Distance	Height Difference	Mark	Direction	Horiz. Distance	Height Difference
			above standpt.				above standpt.
			below				below
			above standpt.				above standpt.
			below				below
			above standpt.				above standpt.
			below				below
			above standpt.				above standpt.
			below				below
			above standpt.				above standpt.
			below				below
			above standpt.				above standpt.
			below				below

Prepared by: *[Signature]* 23.1


Checked: *[Signature]*

Noted on U.T.M. Card



Sr 2735-2 D. West, Government Printer

STATION **TAPITALEE NORTH TS 4279**



Owner's Name: **In BLACK ASH MATURE RESERVE**
 Address: **(Morton National Park)**
 Phone:

Current Occupant:

ACCESS
 Access Report of 11/11/1977 was found suitable/unsuitable.

- 0.0km Berry P.O. Take hwy south
- 1-1 Turn R towards Kangaroo Valley
- 3-6 Pass BUNDEWALLAH road on R
- 7-5 Pass road on R
- 8-3 Take R fork
- 9-4 Take track on L
- 10-6 Park vehicle. would be 30-40min walk.

This section to be completed by officer constructing pillar.

Original station mark found/not found.

Description of mark:

Original beacon found/not found.

Description of beacon:

Height Top of Varies to Top Mark:m.

Height of mark:m. above G.L. below G.L.

Diameter of Varies:m. Height of Cairn:m.

Original Beacon has/has not been destroyed by me.

Date	Locality of Station