

CENTRAL MAPPING AUTHORITY

GEODETIC SURVEY OF N.S.W.

GEODETIC STATION RECONNAISSANCE and MAINTENANCE REPORT

Description:

Note: Cross out word or words which do not apply

1. Cleared by lanes bearing.....*HILL HAS A FEW SCATTERED TREES*..... from Trig. Mast
2. Mast & Vanes have been painted white & black respectively.
3. The station/pillar was unpiled/not unpiled/constructed on19....., dimensions now being:
Description of mark.....should be explicit, e.g., S/Steel Pillar Plate, Steel plug, Brass plug, Bolt, G.I. Pipe
Height of mark.....m.....^{above} _{below} rock/concrete; Mark is.....m.....^{above} _{below} G.L.
Height of Top Vanes to Top Mark/Pillar platem. Diameter of Vanes (vertical).....m.
Height of Cairn.....m. Diameter of Cairn.....m. Name Plate found/not found/placed.
Length of Mastm. (approximate if not unpiled)
4. A.....set in conc/rock has been placed/found, bearing.....° M from Mast/Plug/Pillar
5. A.....set in conc/rock has been placed/found, bearing.....° M from Mast/Plug/Pillar
6. A.....set in conc/rock has been placed/found, bearing.....° M from Mast/Plug/Pillar
7. A.....set in conc/rock has been placed/found, bearing.....° M from Mast/Plug/Pillar
8. Action required:.....*NO MARKS FOUND. STATION OF LITTLE VALUE*.....

STANDPOINT:

STANDPOINT:

| Mark | Direction | Horiz. Distance | Height Difference | Mark | Direction | Horiz. Distance | Height Difference |
|------|-----------|-----------------|-------------------------|------|-----------|-----------------|-------------------------|
| | | | above standpt. below | | | | above standpt. below |
| | | | above standpt. below | | | | above standpt. below |
| | | | above standpt. below | | | | above standpt. below |
| | | | above standpt. below | | | | above standpt. below |
| | | | above standpt. below | | | | above standpt. below |
| | | | above standpt. below | | | | above standpt. below |
| | | | above standpt. below | | | | above standpt. below |
| | | | above standpt. below | | | | above standpt. below |

Prepared by: *Bob Carruth*

Checked: *Bob Carruth*

Noted on U.T.M. Card

ST 2733-1

STATION: **TRIANGLE** No: **4448**

MAP SHEET **BATHURST**

SCALE 1:250 000

INSPECTED BY: **A. GARDNER** DATE: **13-5-81**

AUTHORITY: **UMA** FIELD BOOK: **1936**

Checked

Sr: 2733-2 D. West, Government Printer

| STATION | TRIANGLE TS 4448 |
|--|--|
| <p>Owner's Name: NOT CONTACTED</p> <p>Address:</p> <p>Phone:</p> <p>Access Report of 13.8.1988 (was found suitable/unsuitable):</p> <p style="margin-left: 20px;">ACCESS</p> <p style="margin-left: 20px;">FEATURE</p> <p style="margin-left: 20px;">Km</p> <p style="margin-left: 20px;">00</p> <p style="margin-left: 20px;">2.25</p> <p style="margin-left: 20px;">TRIANGLE FLAT INTERSECTION ROCKLEY 13 TRUMKEY 16 BARRABA 26 TAKE ROCKLEY ROAD PARK VEHICLE JUST PAST CUTTING STATION IS ON HILL ON RIGHT. 200M OVER FENCE.</p> | <p>Current Occupant:</p> <p>Address:</p> <p>Phone:</p> |
| <p>This section to be completed by officer constructing pillar.</p> | |
| <p>Original station mark found/not found.</p> <p>Description of mark:</p> <p>Original beacon found/not found.</p> <p>Description of beacon:</p> <p>Height Top of Vanes to Top Markm.</p> <p>Height of markm. above G.L. below</p> <p>Diameter of Vanesm. Height of Cairnm.</p> <p>Original Beacon has/has not been destroyed by me.</p> | <p>Record of Station</p> <p>Date</p> |

