

CENTRAL MAPPING AUTHORITY

Department of Lands

Trigonometrical Survey of N.S.W.

RECONNAISSANCE and MAINTENANCE REPORT

This Trig. Station has been:-

Note: Cross out word or words which do not apply

- ✓ Completely cleared to permit 360° vision to surrounding Trigs.
- ✓ Cleared by lanes bearing from Trig. Mast
- ✓ Trig. Mast & Vanes have been painted white & black respectively.

4. The Trig. was ~~emptied~~/not unpiled, dimensions now being: ~~Original~~ ^{Original} ~~Height~~ ^{Height} ~~Bottom~~ ^{Bottom} ~~Mast~~ ^{Mast} ~~Case~~ ^{Case} ~~Net~~ ^{Net}

Description of mark..... should be explicit, e.g. Steel plug, Brass plug, Bolt, G.I. Pipe

Height of mark..... m above rock/concrete m above below G.L.

Height of Top Vanes to Top Mark..... m. Diameter of Vanes (vertical)..... m.

Height of Cairn..... m. Diameter of Cairn..... m.

Length of Mast..... m. (approximate if not unpiled)

- ✓ A..... set in conc/rock has been placed..... m. bearing..... °M from Trig. Mast
- ✓ A..... set in conc/soil has been placed..... m. bearing..... °M from Trig. Mast
- ✓ A..... set in conc/soil has been placed..... m. bearing..... °M from Trig. Mast
- ✓ A..... set in conc/rock has been placed..... m. bearing..... °M from Trig. Mast

- ✓ Connection..... to..... m. bearing..... °M
- ✓ Connection..... to..... m. bearing..... °M
- ✓ Connection..... to..... m. bearing..... °M
- ✓ Connection..... to..... m. bearing..... °M
- ✓ Diff. Ht. is..... m. ^{above} _{below}
- ✓ Diff. Ht. is..... m. ^{above} _{below}
- ✓ Diff. Ht. is..... m. ^{above} _{below}
- ✓ Diff. Ht. is..... m. ^{above} _{below}

Prepared by: gpharm 21/12/77 Checked: gpharm Noted on U.T.M. Card

STATION TRIGALANA T.S. 4450

Co: _____ Pts: _____

Map Sheet: WIRRIYA 1:50 000 No: 8430-N

Inspected by: J. SHERWIN Date: 11/77

Authority: C.M.A. Field Book: _____

Beacon Diagram: Not to Scale



Date	Record of Station

Checked

