

GEODETIC SURVEY OF N.S.W.

CENTRAL MAPPING AUTHORITY

GEODETIC STATION RECONNAISSANCE and MAINTENANCE REPORT

- Description:
- Cleared by James bearing. Note: Cross out word or words which do not apply from Trig. Mast
  - Mast & Vanes have been painted white & black respectively.
  - The station/pillar was unplaced/not unplaced/constructed on 19 dimensions now being:
- Description of mark should be explicit, e.g., S/Steel Pillar Plate, Steel plug, Brass plug, Bolt, G.I. Pipe
- Height of mark above/below rock/concrete. Mark is above/below G.L.
- Height of Top Vanes to Top Mark/Pillar plate m. Diameter of Vanes (vertical) m.
- Height of Cairn m. Diameter of Cairn m. Name Plate found/not found/placed.
- Length of Mast m. (approximate if not unplaced) mast destroyed
- A set in conc/rock has been placed/found, bearing ° M from Mast/Plug/Pillar
  - A set in conc/rock has been placed/found, bearing ° M from Mast/Plug/Pillar
  - A set in conc/rock has been placed/found, bearing ° M from Mast/Plug/Pillar
  - A set in conc/rock has been placed/found, bearing ° M from Mast/Plug/Pillar
8. Action required: Mast needs to be replaced approx 3 days clearing. Station suitable for pillar construction

STANDPOINT:

Mark	Direction	Horiz. Distance	Height Difference	Mark	Direction	Horiz. Distance	Height Difference
			above standpt.				above standpt.
			below				below
			above standpt.				above standpt.
			below				below
			above standpt.				above standpt.
			below				below
			above standpt.				above standpt.
			below				below
			above standpt.				above standpt.
			below				below
			above standpt.				above standpt.
			below				below

Prepared by: *[Signature]* 24/4/78 Checked: *[Signature]* Noted on U.T.M. Card

ST 2733-1

STATION: **TRUNDLE** No.: **4456**

MAP SHEET SCALE 1:250 000 **Narramine**

INSPECTED BY: **P.K. BARMOLA** DATE: **23/9/78**

AUTHORITY: **C.M.A.** FIELD BOOK:

