

CENTRAL MAPPING AUTHORITY

GEODETIC SURVEY OF N.S.W.

GEODETIC STATION RECONNAISSANCE and MAINTENANCE REPORT

Description:

- Note: Cross out word or words which do not apply*
- Cleared by lanes bearing Timbered 360 1 day clearing from Trig, Mast
  - ~~Mast & Vanes have been painted white & black respectively.~~ Beacon in poor condition
  - The station ~~marker~~ was ~~unplaced/not unplaced/constructed on~~ 19 dimensions now being: Description of mark Steel Pillar Plate, Steel plug, Brass plug, Bolt, G.I. Pipe
  - Height of mark 1.4 m. <sup>above</sup> rock/concrete; Mark is 2.5 m. <sup>above</sup> G.L.
  - Height of Top Vanes to Top Mark/Fitter plate 0.93 m. Diameter of Vanes (vertical) 0.93 m. on ground
  - Height of Cairn 1.4 m. Diameter of Cairn 2.5 m. Name Plate found/not found/placed.
  - Length of Mast 1.4 m. (approximate if not unplaced)
  - A set in conc/rock has been placed/found, bearing 0° M from Mast/Plug/Pillar
  - A set in conc/rock has been placed/found, bearing 0° M from Mast/Plug/Pillar
  - A set in conc/rock has been placed/found, bearing 0° M from Mast/Plug/Pillar
  - A set in conc/rock has been placed/found, bearing 0° M from Mast/Plug/Pillar

Action required: CANYON LEIGH

STANDPOINT: 1:31680

Mark	Direction	Horiz. Distance	Height Difference	Mark	Direction	Horiz. Distance	Height Difference
			above standpt.				above standpt.
			below				below
			above standpt.				above standpt.
			below				below
			above standpt.				above standpt.
			below				below
			above standpt.				above standpt.
			below				below
			above standpt.				above standpt.
			below				below
			above standpt.				above standpt.
			below				below

Prepared by: *[Signature]* Checked: *[Signature]*

Noted on U.T.M. Card

SI 2738-1

STATION: **URINGALLA** No.: **TS 4529**

MAP SHEET SCALE 1:250 000 **Wollongong**

INSPECTED BY: **A. Sivertsen** DATE: **8-11-78**

AUTHORITY: **CMA** FIELD BOOK: **1717**

Station Diagram

North

Not to Scale

330 340 350 360 370 380 390


310 320 330 340 350 360 370 380 390 400 410 420 430 440

220 230 240 250 260 270 280 290 300 310 320 330 340 350 360 370 380 390 400 410 420 430 440

△ is on low hill  
- poor site

+

Checked

ST 2733-2 D. West, Government Printer Beacon Diagram Not to Scale 	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 50%; vertical-align: top;">                             STATION <b>URINGALLA TS 4529</b> </td> <td style="width: 50%; vertical-align: top;">                             Current Occupant: .....                              Address: .....                              Phone: .....                         </td> </tr> <tr> <td style="vertical-align: top;">                             Owner's Name: <b>CHILTON PASTORAL CO</b>                              Address: .....                              Phone: .....                         </td> <td style="vertical-align: top;">                             Phone: <b>841521</b>                              ACCESS                         </td> </tr> <tr> <td colspan="2" style="vertical-align: top;">                             Access Report of <b>8/1/1978</b> was found suitable/unsuitable.  <b>From MARULAN take Hwy. north for about 13.2 km</b>  <b>0-0 Turn L towards CANYONLEIGH</b>  <b>0-9 Cwy.</b>  <b>4-2 Turn left over grid "CHILTON PARK" then over bridge</b>  <b>4-4 Grid</b>  <b>4-5 Owners house on L</b>  <b>4-7 Grid</b>  <b>5-5 " "</b>  <b>6-2 " "</b>  <b>6-7 Turn R over dam then R again</b>  <b>7-6 Turn L just before grid</b>  <b>7-7 Δ URINGALLA</b> </td> </tr> </table>	STATION <b>URINGALLA TS 4529</b>	Current Occupant: ..... Address: ..... Phone: .....	Owner's Name: <b>CHILTON PASTORAL CO</b> Address: ..... Phone: .....	Phone: <b>841521</b> ACCESS	Access Report of <b>8/1/1978</b> was found suitable/unsuitable. <b>From MARULAN take Hwy. north for about 13.2 km</b> <b>0-0 Turn L towards CANYONLEIGH</b> <b>0-9 Cwy.</b> <b>4-2 Turn left over grid "CHILTON PARK" then over bridge</b> <b>4-4 Grid</b> <b>4-5 Owners house on L</b> <b>4-7 Grid</b> <b>5-5 " "</b> <b>6-2 " "</b> <b>6-7 Turn R over dam then R again</b> <b>7-6 Turn L just before grid</b> <b>7-7 Δ URINGALLA</b>		<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 50%;"></td> <td style="width: 50%; text-align: center;">Record of Station</td> </tr> <tr> <td style="text-align: center;">Date</td> <td></td> </tr> <tr> <td style="height: 40px;"></td> <td></td> </tr> <tr> <td style="height: 40px;"></td> <td></td> </tr> </table>		Record of Station	Date					
STATION <b>URINGALLA TS 4529</b>	Current Occupant: ..... Address: ..... Phone: .....															
Owner's Name: <b>CHILTON PASTORAL CO</b> Address: ..... Phone: .....	Phone: <b>841521</b> ACCESS															
Access Report of <b>8/1/1978</b> was found suitable/unsuitable. <b>From MARULAN take Hwy. north for about 13.2 km</b> <b>0-0 Turn L towards CANYONLEIGH</b> <b>0-9 Cwy.</b> <b>4-2 Turn left over grid "CHILTON PARK" then over bridge</b> <b>4-4 Grid</b> <b>4-5 Owners house on L</b> <b>4-7 Grid</b> <b>5-5 " "</b> <b>6-2 " "</b> <b>6-7 Turn R over dam then R again</b> <b>7-6 Turn L just before grid</b> <b>7-7 Δ URINGALLA</b>																
	Record of Station															
Date																
This section to be completed by officer constructing pillar. Original station mark found/not found. Description of mark: ..... Original beacon found/not found. Description of beacon: ..... Height Top of Varies to Top Mark.....m. Height of mark.....m. above G.L. above rock/stone.....m. below Diameter of Varies.....m. Height of Cairn.....m. Original Beacon has/has not been destroyed by me.																