

CENTRAL MAPPING AUTHORITY

GEODETIC SURVEY OF N.S.W.

GEODETIC STATION RECONNAISSANCE and MAINTENANCE REPORT

Description:

1. Cleared by lances bearing.....
Note: Cross out word or words which do not apply
2. Mast & Vanes have been painted white & black respectively, and cairn of rocks.
3. The station/pillar was unpiled/not unpiled/constructed on..... 19....., dimensions now being:
Description of mark.....should be explicit, e.g., S/Steel Pillar Plate, Steel plug, Brass plug, Bolt, G.I. Pipe
- Height of mark.....m. ^{above} rock/concrete; Mark is.....m. ^{above} G.L.
- Height of Top Vanes to Top Mark/Pillar platem. Diameter of Vanes (vertical).....m.
- Height of Cairn.....m. Diameter of Cairn.....m. Name Plate found/not found/placed.
- Length of Mast.....m. (approximate if not unpiled)
4. A.....set in conc/rock has been placed/found, bearing.....° M from Mast/Plug/Pillar
5. A.....set in conc/rock has been placed/found, bearing.....° M from Mast/Plug/Pillar
6. A.....set in conc/rock has been placed/found, bearing.....° M from Mast/Plug/Pillar
7. A.....set in conc/rock has been placed/found, bearing.....° M from Mast/Plug/Pillar
8. Action required: *Station Needs Clearing*

STANDPOINT:

Mark	Direction	Horiz. Distance	Height Difference	Mark	Direction	Horiz. Distance	Height Difference
			above standpt. below				above standpt. below
			above standpt. below				above standpt. below
			above standpt. below				above standpt. below
			above standpt. below				above standpt. below
			above standpt. below				above standpt. below
			above standpt. below				above standpt. below
			above standpt. below				above standpt. below

Prepared by: *[Signature]*

Checked:

Noted on U.T.M. Card

SI 2733-1

STATION: *Wambarangong* No.: *4594*

MAP SHEET SCALE 1:250 000 *Narramine*

INSPECTED BY: *P.K. Bamola* DATE: *Dug 78*

AUTHORITY: *CMA* FIELD BOOK:

8: 2733 - 2 D. West, Government Printer

STATION *Wam Danga Long TS 4594*

Beacon Diagram

Not to Scale

Owner's Name:
 Address:
 Phone:

Current Occupant:
 Address:
 Phone:

Aug 1978
 ACCESS
 Access Report of/19..... was found suitable/unavailable.

*Refer Sappa Balga 1:50 000 Sheet
 Access via "Mudgengar" property
 Sminis walk.*

This section to be completed by officer constructing pillar.

Original station mark found/not found.

Description of mark:

Original beacon found/not found.

Description of beacon:

Height Top of Vanes to Top Mark.....m.
 above G.L.
 below

Height of mark.....m. rocks/conc.....m. above G.L.
 below

Diameter of Vanesm. Height of Cairnm.

Original Beacon has/not been destroyed by me.

Date

Record of Station