

CENTRAL MAPPING AUTHORITY

GEODETIC SURVEY OF N.S.W.

GEODETIC STATION RECONNAISSANCE and MAINTENANCE REPORT

- Description: *Note: Cross out word or words which do not apply*
1. Cleared by lanes bearing..... from Trig. Mast
 2. Mast & Vanes have been painted white & black respectively.
 3. The station/pillar was unpiled/not unpiled/constructed on.....19....., dimensions now being: Description of mark.....should be explicit, e.g., S/Steel Pillar Plate, Steel plug, Brass plug, Bolt, G.I. Pipe
Height of mark.....m, above rock/concrete; Mark is.....m, above G.L.
Height of Top Vanes to Top Mark/Pillar platem. Diameter of Vanes (vertical).....m.
Height of Cairn.....m. Diameter of Cairn.....m. Name Plate found/not found/placed.
Length of Mast.....m. (approximate if not unpiled)
 4. A.....set in conc/rock has been placed/found, bearing.....° M from Mast/Plug/Pillar
 5. A.....set in conc/rock has been placed/found, bearing.....° M from Mast/Plug/Pillar
 6. A.....set in conc/rock has been placed/found, bearing.....° M from Mast/Plug/Pillar
 7. A.....set in conc/rock has been placed/found, bearing.....° M from Mast/Plug/Pillar
 8. Action required:.....

STANDPOINT:

Mark	Direction	Horiz. Distance	Height Difference	Mark	Direction	Horiz. Distance	Height Difference
			above below standpt.				above below standpt.
			above below standpt.				above below standpt.
			above below standpt.				above below standpt.
			above below standpt.				above below standpt.
			above below standpt.				above below standpt.
			above below standpt.				above below standpt.
			above below standpt.				above below standpt.

Prepared by: *[Signature]* 27/11/18
Checked: *[Signature]*

Notes on U.I.M. Card

St 2733-1


STATION: **MOORAGEE** No: **1852**
 MAP SHEET SCALE 1:250 000 **GOULBURN**
 INSPECTED BY: **M.L. Moorehead** DATE: **20/11/18**
 AUTHORITY: **CMA** FIELD BOOK: **1711**

Station Diagram

Not to Scale
 The plot in fair condition
 needs new mast + vanes
 Will could only be towered very
 dense but only small timber
 upto 3 days a base.

Checked

Sr. 2738-2 D. West, Government Printer



This section to be completed by officer constructing pillar.

Original station mark found/not found.

Description of mark:

Original beacon found/not found.

Description of beacon:

Height Top of Varies to Top Mark.....m.

Height of mark.....m. above G.L. / below G.L.

Diameter of Vases.....m. Height of Cairn.....m.

Original Beacon has/has not been destroyed by me.

STATION	WOORAGEE	TS 4852
Owner's Name: <u>J T MENZIES</u>	Current Occupant:	
Address: <u>WOORAGEE</u>	Address:	
Phone: <u>BANANGBY</u>	Phone:	
Phone: <u>SZ - 8143</u>	Phone:	
<u>ACCESS</u>		
Access Report of <u>20/11/1978</u> was found suitable/unsuitable.		
<u>Km</u>	<u>ACCESS</u>	
0.00	TARALEGA RD HEADS SOUTH TOWARDS GULLBURN.	
0.10	TURN LEFT FOLLOW RD TO 'BANANGBY 16'	
0.20	PASS RD TO 'OMARU' ON LEFT. ✓	
0.20	PASS RD ON LEFT TO 'NEWBUNDLAND'	
12.60	TURN LEFT THROUGH GATE 'WOORAGEE'	
13.35	GO THROUGH GATE OPPOSITE BACK OF 'HOUSE' HEAD UP RIDGE TO TRACK UNDER POWER LINE (HOUSE OWNER MR BUS MENZIES)	
13.50	GATE FOLLOW TRACK	
14.70	TURN RIGHT FOLLOW LANDINGS GROUND + TRACK	
15.40	GO THROUGH GATE NEAR SHEEP RACE. FOLLOW TRACK	
16.50	GO THROUGH GATE ON LEFT FOLLOW UP LAY SIDE OF FENCELINE	
16.80	TRIP ON LEFT IN TIMBER.	

Date	Record of Station