

CENTRAL MAPPING AUTHORITY

GEODETIC SURVEY OF N.S.V.


GEODETIC STATION RECONNAISSANCE and MAINTENANCE REPORT

STATION: **S.M.A. 770** No.: **488**

MAP SHEET SCALE 1:250 000 **TANTANGARA** 1:100 000

INSPECTED BY: **R. COOK** DATE: **10-3-79**

AUTHORITY: **C.M.A.** FIELD BOOK:



- Description:
- Note: Cross out word or words which do not apply
- Cleared by lanes bearing..... from Trig, Mast
 - Mast & Vanes have been painted white & black respectively.
 - The station/pillar was unpiled/not unpiled/constructed on..... 19....., dimensions now being: Description of mark.....should be explicit, e.g, S/Steel Pillar Plate, Steel plug, Brass plug, Bolt, G.I. Pipe
- Height of mark.....m. ^{above}/_{below} rock/concrete; Mark is.....m. ^{above}/_{below} G.L.
- Height of Top Vanes to Top Mark/Pillar platem. Diameter of Vanes (vertical).....m.
- Height of Cairn.....m. Diameter of Cairn.....m. Name Plate found/not found/placed.
- Length of Mast.....m. (approximate if not unpiled)
- A.....set in conc/rock has been placed/found, bearing.....°M from Mast/Plug/Pillar
 - A.....set in conc/rock has been placed/found, bearing.....°M from Mast/Plug/Pillar
 - A.....set in conc/rock has been placed/found, bearing.....°M from Mast/Plug/Pillar
 - A.....set in conc/rock has been placed/found, bearing.....°M from Mast/Plug/Pillar

8. Action required: **NOT RECONSIDERED. MARK...MIST...ROCK...COVERED IN REVERSE. TIMBER...FALLEN...TIMBER...and Heavy undergrowth 10mm wank**

STANDPOINT:

Mark	Direction	Horiz. Distance	Height Difference	Mark	Direction	Horiz. Distance	Height Difference
			above standpt.				above standpt.
			below standpt.				below standpt.
			above standpt.				above standpt.
			below standpt.				below standpt.
			above standpt.				above standpt.
			below standpt.				below standpt.
			above standpt.				above standpt.
			below standpt.				below standpt.
			above standpt.				above standpt.
			below standpt.				below standpt.

Prepared by: *Rodney Cook* Checked: *Checked*

CS

St 2733-2 D. West, Government Printer	STATION S.M.A. 770 TS 488	Owner's Name: Address: <i>Situated within the</i> <i>KASUNING NATIONAL PARK</i> Phone: Current Occupant: Address: Phone:	ACCESS Access Report of O.I. A./1972 was found suitable/unsuitable.		Record of Station Date 10-3-79 Reason: <i>Access taken off the Tanjagara 1:25,000</i>
Beacon Diagram Not to Scale		This section to be completed by officer constructing pillar. Original station mark found/not found. Description of mark: Original beacon found/not found. Description of beacon: Height Top of Vanes to Top Markm. Height of mark:m. above rock/cornicem. below G.L. Diameter of Vanesm. Height of Cairnm. Original Beacon has/not been destroyed by me.			