

CENTRAL MAPPING AUTHORITY

GEODETTIC SURVEY OF N.S.W.

GEODETTIC STATION RECONNAISSANCE and MAINTENANCE REPORT

Description:

Note: Cross out word or words which do not apply

1. Cleared by lanes bearing..... from Trig. Mast
2. Mast & Vanes have been painted white & black respectively.
3. The station/pillar was unpiled/not unpiled/constructed on.....19....., dimensions now being: Description of mark.....should be explicit, e.g., S/Steel Pillar Plate, Steel plug, Brass plug, Bolt, G.I. Pipe  
Height of mark.....m. <sup>above</sup> rock/concrete; Mark is.....m. <sup>above</sup> G.L.  
Height of Top Vanes to Top Mark/Pillar plate.....m. Diameter of Vanes (vertical).....m.  
Height of Cairn.....m. Diameter of Cairn.....m. Name Plate found/not found/placed.  
Length of Mast.....m. (approximate if not unpiled)
4. A.....set in conc/rock has been placed/found, bearing.....°M from Mast/Plug/Pillar
5. A.....set in conc/rock has been placed/found, bearing.....°M from Mast/Plug/Pillar
6. A.....set in conc/rock has been placed/found, bearing.....°M from Mast/Plug/Pillar
7. A.....set in conc/rock has been placed/found, bearing.....°M from Mast/Plug/Pillar
8. Action required:.....

STANDPOINT:

Mark	Direction	Horiz. Distance	Height Difference	Mark	Direction	Horiz. Distance	Height Difference
			above standpt				below standpt
			below				above standpt
			above standpt				below
			below				above standpt
			above standpt				below
			below				above standpt
			above standpt				below
			below				above standpt
			above standpt				below
			below				above standpt

Prepared by: *[Signature]*

Checked: *[Signature]*

Noted on U.T.M. Card

St 2739-1

STATION: *Mount Johnson G.S.* No.: *5086*  
 MAP SHEET: *WOLLONSONG*  
 SCALE 1:250,000  
 INSPECTED BY: *M.L. Speers* DATE: *17-1-79*  
 AUTHORITY: *C.M.A.* FIELD BOOK: *1720*

Station Diagram

North  
 Not to Scale  
 No sign of trig. for Hill Covered with Olan-tans 2 to 3 metres high.

Checked

GS

<p>St. 2735 - 2 D. West. Government Printer</p> <p>Beacon Diagram</p>	<p>STATION <i>Mount Johnson G.S. TS 5086</i></p>	<p>Owner's Name: .....                  Address: .....                  Phone: .....</p> <p>Current Occupant: .....                  Address: .....                  Phone: .....</p> <p>Access Report of <i>17/1/10</i> was found suitable/unsuitable.</p> <p style="text-align: center;"><b>ACCESS</b></p> <p><i>Direction</i></p> <p><i>Albion Park Hotel. Albion Park. Take Road to Robertson</i></p> <p><i>Turn right into Calderwood Rd.</i></p> <p><i>Turn right ahead</i></p> <p><i>Turn left into House 'Meadowood' (Owners) Follow track</i></p> <p><i>around to left of house and follow fence line</i></p> <p><i>Use gate. Follow track across dam wall and keep following fence</i></p> <p><i>Keep right onto track around side of hill.</i></p> <p><i>Keep left follow steep track up spur</i></p> <p><i>Top of hill</i></p> <p>km                  0.00                  0.85                  2.90                  4.70                  4.95                  5.40                  5.60                  5.90</p>
<p>Not to Scale</p>		<p>Date</p> <p>Record of Station</p>
<p>This section to be completed by officer constructing pillar.</p> <p>Original station mark found/not found.</p> <p>Description of mark: .....</p> <p>Original beacon found/not found.</p> <p>Description of beacon: .....</p> <p>Height Top of Vane to Top Mark .....m.</p> <p>Height of mark .....m. above G.L. / below G.L.</p> <p>Diameter of Vane .....m. Height of Cairn .....m.</p> <p>Original Beacon has/has not been destroyed by me.</p>		