

GEODETTIC SURVEY OF NSUK

CENTRAL MAPPING AUTHORITY

GEODETTIC STATION RECONNAISSANCE and MAINTENANCE REPORT

- Description: *Note: Cross out word or words which do not apply*
- Cleared by lanes bearing..... from Trig. Mast
 - Mast & Vanes have been painted white & black respectively.
 - The station/~~pillar~~ was applied/not applied/~~constructed or~~.....*19*..... dimensions ~~new being~~.....
Description of mark.....should be explicit, e.g., S/Steel Pillar Plate, Steel plug, Brass plug, Bolt, G.I. Pipe
Height of mark.....m. ^{above} rock/concrete; Mark is.....m. ^{above} G.L. _{below}
Height of Top Vanes to Top Mark/Pillar platem. Diameter of Vanes (vertical).....*1.05* ✓m.
Height of Cairn.....m. Diameter of Cairn.....*1.6* ✓m. Name Plate ~~found/not found/phase~~
Length of Mast*2.30* ✓m. (approximate if not unplied)
 - A.....set in conc/rock has been placed/round, bearing.....°M from Mast/Plug/Pillar
 - A.....set in conc/rock has been placed/round, bearing.....°M from Mast/Plug/Pillar
 - A.....set in conc/rock has been placed/round, bearing.....°M from Mast/Plug/Pillar
 - A.....set in conc/rock has been placed/round, bearing.....°M from Mast/Plug/Pillar
 - Action required: *Mast. Top Mark. Found in Conc. Condition - CHINA SENSATION*
AKELPZ

STANDPOINT:

Mark	Direction	Horiz. Distance	Height Difference	Mark	Direction	Horiz. Distance	Height Difference
			above standpt.				above standpt.
			below				below
			above standpt.				above standpt.
			below				below
			above standpt.				above standpt.
			below				below
			above standpt.				above standpt.
			below				below
			above standpt.				above standpt.
			below				below
			above standpt.				above standpt.
			below				below

Prepared by: *NY* *Loch*

Checked:

Note: on U.T.M. Card

SI 2733-1

STATION: *NEIKAH* No.: *5202*
 MAP SHEET SCALE 1:250 000 *HASTINGS*
 INSPECTED BY: *G. DICKSON* DATE: *18-07-79*
 AUTHORITY: *C.M.A* FIELD BOOK: *1706*

Station Diagram
 Not to Scale
 Checked

STATION MEIKAPH TS 5202	Owner's Name: Address: Phone: Access Report of...../...../19.....was found suitable/unsuitable.	Current Occupant: Address: Phone: ACCESS
Beacon Diagram Not to Scale		
This section to be completed by officer constructing pillar. Original station mark found/ not found .		
Description of mark: Original beacon found/not found.		
Description of beacon <i>CHAIN WOOD PILE NOT MARKED</i> Height Top of Vanes to Top Mark m. above below G.L. Height of mark m. above below rock/conc m. Diameter of Vanes m. Height of Cairn m. Original Beacon has/has not been destroyed by me.		
Date	Record of Station	