

GEODETTIC SURVEY OF M.S.W.

CENTRAL MAPPING AUTHORITY


GEODETTIC STATION RECONNAISSANCE and MAINTENANCE REPORT

STATION: CORNER No: 5269

MAP SHEET SCALE 1:250 000 WANGANUI DISTRICT

INSPECTED BY: KEITH HADDON DATE: 14/07/19

AUTHORITY: C.M.A. FIELD BOOK:



- Description:
- Cleared by lanes bearing..... Note: Cross out word or words which do not apply
  - Mast & Vanes have been painted white & black respectively. .... from Trig. Mast
  - The station/pillar was unpiled/not unpiled/constructed on ..... 19....., dimensions now being: Description of mark..... should be explicit, e.g., S/Steel Pillar Plate, Steel plug, Brass plug, Bolt, G.I. Pipe  
Height of mark.....m. above below rock/concrete; Mark is.....m. above below G.L.
  - Height of Top Vanes to Top Mark/Pillar plate .....m. Diameter of Vanes (vertical).....m.
  - Height of Cairn.....m. Diameter of Cairn.....m. Name Plate found/not found/placed.
  - Length of Mast .....m. (approximate if not unpiled)
  - A.....set in conc/rock has been placed/found, bearing.....° M from Mast/Plug/Pillar
  - A.....set in conc/rock has been placed/found, bearing.....° M from Mast/Plug/Pillar
  - A.....set in conc/rock has been placed/found, bearing.....° M from Mast/Plug/Pillar
  - A.....set in conc/rock has been placed/found, bearing.....° M from Mast/Plug/Pillar
  - Action required:.....

STANDPOINT:


Mark	Direction	Horiz. Distance	Height Difference	Mark	Direction	Horiz. Distance	Height Difference
			above standpt				above standpt
			below				below
			above standpt				above standpt
			below				below
			above standpt				above standpt
			below				below
			above standpt				above standpt
			below				below
			above standpt				above standpt
			below				below
			above standpt				above standpt
			below				below

Prepared by: Keith Haddon 21-11-78

Checked:

Checked

STATION CORNER TS- 5219



Owner's Name: .....  
 Address: .....  
 Phone: .....

Current Occupant: .....  
 Address: .....  
 Phone: .....

Nov-1978  
 ACCESS  
 Access Report of ...../19.....was found suitable/unsuitable.

From North Albany Roundabout (with traffic light and Leighton Post Office) proceed North West along Union Road for approx 7-km. Turn left at top of hill onto gravel road and proceed 2.5 km to T-junction.  
 0.0 Proceed straight ahead at T-junction.  
 0.3 Take left track through gate and turn left.  
 0.5 Gate  
 0.9 Gate  
 1.4 Gate.  
 1.8 Straight ahead.  
 2.0 Through gate and turn right  
 2.2 Through gate and follow track along fence  
 2.8 Through left hand gate and follow track to right.  
 3.0 Turn left off track and find way to top of hill  
 3.1 Top of Hill.

This section to be completed by officer constructing pillar.

Original station mark found/not found.

Description of mark: .....

Original beacon found/not found.

Description of beacon: .....

Height Top of Vanes to Top Mark.....m.

Height of mark.....m. above G.L. below

Diameter of Vanes .....m. Height of Cairn .....m.

Original Beacon has/has not been destroyed by me.

Date	Record of Station
Nov 78	Not found