

75 193

Department of Lands
 Reconnaissance and Maintenance Report No. 452
 STATION HERMITAGE (D) TS 5452
 Ph: _____

Map Sheet: _____ No: _____
 Inspected by: _____ Date: _____
 Authority: _____ Field Book: _____
 Beacon Diagram: _____ Not to Scale

Note: Cross out word or words which do not apply

This Trig. Station has been:-

1. Completely cleared to permit 360° vision to surrounding Trigs.
2. Cleared by lances bearing from Trig. Mast

STATION HERMITAGE No. 52 RESERVOIR R.L. 98.11 (M.A. Points) W.B. 21

ABSTRACT OF OBSERVATIONS

To	Dist. in metres	Direction or Vert. Angle	Variance	Observer	Date	Weight	Adjustment	Observer	Date
Mobbs Hill Res.	0	00	00.0	M.W. JONES	1975	5.64		COOPER	MAY
Marsfield Res. Satellite	39	06	39.0			10.00		PERSONE	6.11.77
Watsonys Res. Aerial	61	36	51.3						
Chatswood T.S.	152	53	187.3						
Harbour Bridge Light	191	14	217.3						
Ryde Blue Cross	280	47	41.5						
Hermitage Tams Satellite	330	56	11.5						
Hermitage Res. Vane	332					0.003			

All directions corrected to centre R.L. 98.496

13. Diff. Ht. m. above below
 14. Diff. Ht. is m. above below
 15. Diff. Ht. is m. above below
 16. Diff. Ht. is m. above below

Prepared by: _____ Checked: _____

Record of Station

Date	Record of Station

