

7-5-193

Department of Lands  
 STATION TS 2967 MANGERTON (P)

Integrative survey of N.S.W.  
 RECONNAISSANCE and MAINTENANCE REPORT

This Trig. Station has been:-


Note: Cross out word or words which do not apply

1. Completely cleared to permit 360° vision to surrounding trigs.
2. Cleared by lanes bearing..... from Trig. Mast
3. Trig. Mast & Vanes have been painted white & black respectively.
4. The Trig. was unpiled/not unpiled, dimensions now being:

Co: CAMDEN  
 Map Sheet: WOLLONGONG  
 Inspected by:  
 Authority: MWS & D  
 Date: No: 5023  
 Field Book: -  
 Beacon Diagram Not to Scale

ABSTRACT OF OBSERVATIONS

To	R.L. (metres)	Direction or Vert. Angle	Variance	Observer	Date	Dist. in metres (R.L.S.L.)	Inst.	Observer	Date
Reverse for Location Diagram	381								
	321								
	313								
	299								
	199								
	181								
	054								
B 19379	00						Steel Platform	RL 106.267	AND



Directions Corrected to centre  
 All Vents corrected ground to ground  
 SEE REAR OF CARD FOR REMARKS

15. Diff. Ht. .... is ..... m. above below
16. Diff. Ht. .... is ..... m. above below

Prepared by: \_\_\_\_\_  
 Checked: \_\_\_\_\_

Date	Record of Station

