

GEODETTIC SURVEY OF N.S.W.

CENTRAL MAPPING AUTHORITY

GEODETTIC STATION RECONNAISSANCE and MAINTENANCE REPORT

Description:

- 1. Cleared by lanes bearing *146* *Note: Cross out word or words which do not apply* from Trig. Mast
- 2. Mast & Vanes have been painted white & black respectively. ✓
- 3. The ~~station/pillar~~ was ~~unmarked/removed~~ constructed on *18.44* *Intensity 19.8.00*, dimensions now being: Description of mark: *Red top* *Red*; should be explicit, e.g., S/Steel Pillar Plate, Steel plug, Brass plug, Bolt, G.I. Pipe
Height of mark: *1.272* m. *above* *Rock* *cross-stake*; *✓* Mark is *1.272* m. *above* G.L.
Height of Top Vanes to Top ~~mark~~/Pillar plate *1.445* m. *✓* Diameter of Vanes (vertical) *2.250* m.
Height of Cairn *0.00* m. Diameter of Cairn *0.00* m. Name Plate ~~found~~/not ~~found~~/placed.
Length of Mast *0.00* m. (approximate if not unplied)
- 4. A *0.00* set in conc/rock has been placed/found, bearing *0.00*°M from Mast/Plug/Pillar
- 5. A *0.00* set in conc/rock has been placed/found, bearing *0.00*°M from Mast/Plug/Pillar
- 6. A *0.00* set in conc/rock has been placed/found, bearing *0.00*°M from Mast/Plug/Pillar
- 7. A *0.00* set in conc/rock has been placed/found, bearing *0.00*°M from Mast/Plug/Pillar
- 8. Action required: *Construction by S.A.M.*

STANDPOINT:

Mark	Direction	Horiz. Distance	Height Difference	Mark	Direction	Horiz. Distance	Height Difference
			above standpt				above standpt
			below standpt				below standpt
			above standpt				above standpt
			below standpt				below standpt
			above standpt				above standpt
			below standpt				below standpt
			above standpt				above standpt
			below standpt				below standpt
			above standpt				above standpt
			below standpt				below standpt

Prepared by: *P. Berts*

Checked:

Named on U.T.M. Grid

Checked

STATION: *WARRENDAINE (P)*
 MAP SHEETS: *Shirley - 1000 - 83 - 0*
 SCALE 1:250 000
 No.: *7295*
 SCALE 1:100 000
 INSPECTED BY: *P. Berts*
 DATE: *23/1/89*
 AUTHORITY: *C.M.A.*
 FIELD BOOK: *1964*

Station Diagram

North

Not to Scale

GS 24

<p>STATION <u>WARRENSIDE</u> <u>SHARPES ROAD (R-0)</u> IS <u>7295</u></p>	<p>Owner's Name: <u>ORANGE CITY COUNCIL</u> Address: <u>MR GREGG BOWEN</u> <u>ENGINEERS DEPARTMENT</u> Phone: <u>231187</u></p> <p>Current Occupant: Address: Phone:</p> <p>Access: <u>231187</u></p> <p>Access Report of <u>23/1/1988</u> was found suitable/unavailable. <u>VENTURE</u> <u>ORANGE RST OFFICE IN SUMMER STREET ROAD WEST</u> <u>TURN LEFT INTO ANSON STREET</u> <u>TURN RIGHT AT LEFT HAND BEND INTERSECTION OF ANSON ST & SHARPES RD.</u> <u>TURN LEFT THROUGH LOCKED DOUBLE IRON GATES</u> <u>267</u> <u>279</u> <u>285</u> <u>THROUGH LOCKED DOUBLE IRON GATES</u> <u>LOCKED DOOR TO STEEL LOADER & WALKWAY</u> NOTE: <u>KEY AVAILABLE FROM MR GREGG BOWEN</u> <u>OR C.M.A. BATHURST.</u></p>
<p>Beacon Diagram: Not to Scale</p>	<p>This section to be completed by officer constructing pillar.</p> <p>Original station mark found/not found.</p> <p>Description of mark: <u>None. Substituted</u></p> <p>Original beacon found/not found.</p> <p>Description of beacon:</p> <p>Height Top of Vanes to Top Markm.</p> <p>Height of markm. above G.L. below rock/concm. below</p> <p>Diameter of Vanesm. Height of Cairnm.</p> <p>Original Beacon has/has not been destroyed by me.</p>
	<p>Date</p> <p>Record of Station</p>