



GS 24

<p>9. 2730-2 D. West. Government Printer</p> <p>Beacon Diagram</p> <p>Not to Scale</p>	<p>STATION</p> <p><b>WARDEN RES IS 7309</b></p>	<p>Owner's Name <b>WARDEN SHINE</b> Current Occupant: .....</p> <p>Address <b>DURGO ST</b> Address: .....</p> <p><b>STEVE THORNTON</b> Phone: .....</p> <p>Phone <b>068 473217 (for ladder)</b></p> <p><u>ACCESS:</u></p> <p>Access Report of <b>21/3/19</b> was found suitable/unsuitable.</p> <p><b>00</b> WARDEN PO. HEAD TOWARDS GULLANORA</p> <p><b>02</b> OVER BRIDGE + CONTINUE TOWARDS GULLANORA</p> <p><b>05</b> STEEL RESERVOIR ON LEFT.</p> <p>A LONG LADDER IS NEEDED TO CLIMB KT PART OF RESERVOIR AND IS AVAILABLE FROM WARDEN SHINE COUNCIL DEPOT DUGGO ST.</p> <p>RESERVOIR NOT SUITABLE FOR ROOFTOP PILLAR</p>
		<p>Date</p> <p>Record of Station</p>
		<p>Height Top of Vanes to Top Mark.....m.</p> <p>Height of mark.....m. above rock/conc.....m. below G.L.</p> <p>Diameter of Vanes.....m. Height of Cairn.....m.</p> <p>Original Beacon has/has not been destroyed by me.</p>

This section to be completed by officer constructing pillar.

Original station mark found/not found.

Description of mark: .....

Original beacon found/not found.

Description of beacon: .....

Height Top of Vanes to Top Mark.....m.

Height of mark.....m. above rock/conc.....m. below G.L.

Diameter of Vanes.....m. Height of Cairn.....m.

Original Beacon has/has not been destroyed by me.