

CENTRAL MAPPING AUTHORITY

GEODETIC SURVEY OF N.S.W.

GEODETIC STATION RECONNAISSANCE and MAINTENANCE REPORT


STATION: BROKEN HILL 5TH BASE No.: 775

Description:

36.0° Note: Cross out word or words which do not apply

1. Cleared by lanes bearing.....
 2. Mast & Vanes have been painted white & black respectively. No mast nor vanes
 3. The station/pillar was unpiled/net unpiled/constructed on 19 MAR 1979, dimensions now being: Description of mark: Steel Pillar. should be explicit, e.g., S/Steel Pillar Plate, Steel plug, Brass plug, Bolt, G.I. Pipe
- Height of mark.....m. above rock/concrete; Mark is.....m. above below G.L.
- Height of Top Vanes to Top Mark/Pillar plate.....m. Diameter of Vanes (vertical).....m.
- Height of Cairn.....m. Diameter of Cairn.....m. Name Plate found/not found/placed.
- Length of Mast.....m. (approximate if not unpiled)
4. A..... set in conc/rock has been placed/found, bearing.....°M from Mast/Plug/Pillar
 5. A..... set in conc/rock has been placed/found, bearing.....°M from Mast/Plug/Pillar
 6. A..... set in conc/rock has been placed/found, bearing.....°M from Mast/Plug/Pillar
 7. A..... set in conc/rock has been placed/found, bearing.....°M from Mast/Plug/Pillar
8. Action required:.....

MAP SHEET SCALE 1:250 000 BROKEN HILL
 INSPECTED BY: A. PATTERSON DATE: 28-3-79
 AUTHORITY: C.M.A. FIELD BOOK:



STANDPOINT:		STANDPOINT:		STANDPOINT:	
Mark	Direction	Horiz. Distance	Height Difference	Mark	Direction
			above standpt.		above standpt.
			below standpt.		below standpt.
			above standpt.		above standpt.
			below standpt.		below standpt.
			above standpt.		above standpt.
			below standpt.		below standpt.
			above standpt.		above standpt.
			below standpt.		below standpt.
			above standpt.		above standpt.
			below standpt.		below standpt.

Prepared by: A. Patterson

Checked: [Signature]

Checked

SR 2733-1

Noted on U.T.M. Card

