

75 01

Department of Lands
 Integrati survey of N.S.W.
RECONNAISSANCE and MAINTENANCE REPORT
 STATION TS 87A BERKELEY RES (P)
 Co: CAMDEN
 Ph: WOLLONGONG
 Map Sheet: WOLLONGONG No: 5023
 Inspected by: — Date: —
 Authority MWS & DFS Field Book:
 Beacon Diagram Not to Scale

Note: Cross out word or words which do not apply

- This Trig. Station has been:-
1. Completely cleared to permit 360° vision to surrounding Trigs.
 2. Cleared by lones bearing..... from Trig. Mast
 3. Trig. Mast & Vanes have been painted white & black respectively.
 4. The Trig. was unpiled/not unpiled, dimensions now being:

ABSTRACT OF OBSERVATIONS

To	R.L. (metres)	Direction or Vert. Angle	Variance	Observer	Date	Dist. in metres at M.S.L.	Variance	Inst.	Observer	Date
Reverse for Location Diagram		32°								
		323								
		313								
		209								
B. 19379		123						Instrument Plate on Top of Pillar		
		114						131.763 AND		
		09						Steel Platform 130.516		
								Concrete Slab 129.633		

Directions Corrected to centre
 All Vert's corrected ground to ground

SEE REAT OF CARD FOR REMARKS

15. Diff. Ht. is ... m. above
16. Diff. Ht. is ... m. below

Prepared by: Checked:

Date _____
 Record of Station _____

