

CENTRAL MAPPING AUTHORITY

GEODETIC SURVEY OF N.S.W.

GEODETIC STATION RECONNAISSANCE and MAINTENANCE REPORT

STATION: **BERRIDALE** No.: **882**

MAP SHEET SCALE 1:250 000 **BEGA**

INSPECTED BY: **G. KEEP** DATE: **19/5/80**

AUTHORITY: FIELD BOOK:

- Description:
1. Cleared by lanes bearing **60° M. only**. Note: Cross out word or words which do not apply
2. ~~Mast & Vanes have been painted white & black respectively.~~
3. The station/pillar was ~~unpiled/not unpiled/constructed on~~ **40** ~~dimensions now being~~
- Description of mark.....should be explicit, e.g., S/Steel Pillar Plate, Steel plug, Brass plug, Bolt, G.I. Pipe
- Height of mark.....m. <sup>above</sup> ~~below~~ rock/concrete; Mark is.....m. <sup>above</sup> ~~below~~ G.L.
- Height of Top Vanes to Top Mark/Pillar plate .....m. Diameter of Vanes (vertical) **0.925**.....m.
- Height of Cairn.....m. Diameter of Cairn **2.0**.....m. Name Plate found/not found/placed.
- Length of Mast **3.5**.....m. (approximate if not unpiled)
4. A.....set in conc/rock has been placed/found, bearing.....° M from Mast/Plug/Pillar
5. A.....set in conc/rock has been placed/found, bearing.....° M from Mast/Plug/Pillar
6. A.....set in conc/rock has been placed/found, bearing.....° M from Mast/Plug/Pillar
7. A.....set in conc/rock has been placed/found, bearing.....° M from Mast/Plug/Pillar
8. Action required... **Needs painting black and white needs clearing in other lanes**.....

STANDPOINT:

Mark	Direction	Horiz. Distance	Height Difference	Mark	Direction	Horiz. Distance	Height Difference
			above standpt				above standpt
			below				below
			above standpt				above standpt
			below				below
			above standpt				above standpt
			below				below
			above standpt				above standpt
			below				below
			above standpt				above standpt
			below				below
			above standpt				above standpt
			below				below

Checked:

Noted on U.T.M. Card

Prepared by: **G. Keep 12/6/80**

Checked

6: 2733-2 D. West, Government Printer

STATION	BERRIDALE	882	
Owner's Name: .....	Current Occupant: .....		
Address: .....	Address: .....		
Phone: .....	Phone: .....		
ACCESS			
Access Report of 15/19/88 was found suitable/unsuitable.			
<u>MILEAGE</u>			
0-00 kms			
0-7 km			
1-1 km			
1-6			
1-9			
2-7			
<u>DESCRIPTION</u>			
From Berridale Post Office drive toward Cooma. Turn left at Cootalantra Road (SP). Travel to "Grieve Hill". See owner.			
Follow track from house in westerly direction			
Pass through Gate			
Pass through fence line			
Take right fork in track			
Gate to track in timber, follow track to trig.			
Trig Site			
Note: Immediate to cairn, mast and vanes has been cleared by bulldozer, no marks were found			
Beacon Diagram		Not to Scale	
This section to be completed by officer constructing pillar.			
Original station mark found/not found.			
Description of mark: .....			
Original beacon found/not found.			
Description of beacon: .....			
Height Top of Vanes to Top Mark.....m.			
Height of mark.....m. above rock/conc.....m. below G.L.			
Diameter of Vanes .....m. Height of Cairn .....m.			
Original Beacon has/has not been destroyed by me.			
Date	Record of Station		